0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh

JW
VB
5-27-88

inspection report

Permit No. ACT/007/022

Inspection Date 5/10/88

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine C.V. Spur Prep Plant ☐ Surface ☐ Underground ☐ Other

County Carbon State Ut

Company Official(s) Dan Guy

State Official(s) Bill Malencik

Time of inspection 8 : 30 ☒ a.m. ☐ p.m. to 3 : 30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection March 31, 1988 Weather conditions Clear/Warm.

Acreage 160 ☐ Permitted 108 ☐ Disturbed 0 ☐ Regraded — ☐ Seeded 160 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 5/10/88

Please number comments to correspond with topics on previous page.

General Comment. A partial inspection was conducted on a dry mine site. The roads appeared to have been water recently. No significant problems were noted.

Diversions: The undisturbed diversion on the northerly portion of the site and adjacent to the fence was cleaned. Most of the fence posts and vegetal material has been removed.

Sediment Pond. Appeared stable no problems detected. Sediment pond inspections for the first quarter of C.Y 1988 have been completed by BCCC and are part of the official mine records.

Coal Processing Waste. The vegetal test plots on the refuse pile have seeded recently fenced, and some plants are emerging. The fencing was necessary in order to keep the rabbits from destroying the seeding test plots.

Copy of report mailed to SLC. For: OSM - Brian Smith/DOGM Joe Helfrich

Copy of report given to Dan Guy - BCCC

" " " filed PFO.

Inspector's signature [signature] 5/11/88. No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE