0013

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022

Inspection Date 02/25/88

Permittee/Operator Name Beaver Creek Coal Company

Business Address P.O. Box 1378

City Price State UT Zip 84501

Mine C.V. Spur ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) Dan Guy

State Official(s) Jim Fricke

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 3:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 1/6/88 Weather conditions clear 50°F

Acreage 160 ☒ Permitted 108 ☒ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 02/25/88

Please number comments to correspond with topics on previous page.

4b. All diversion ditches were functioning and diverting disturbed area runoff to the sediment ponds. Culvert outlets were inspected and the appropriate culverts were checked for riprap installation. The rip rap appears to be stable and well placed.

4e. Water levels were checked in the ground-water monitor wells. Wells CV-6 will require casing repairs.

16d. The recent dry weather has dried out the haul roads. The operator was advised to treat the road surface for dust control.

Copy of report mailed to Dan Guy (BCCC) & Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Jim Fricke No. 22

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE