0004

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center, Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RECEIVED
OCT 10 1989
DIVISION OF
OIL, GAS & MINING

inspection report

Permit No. ACT/007/022
Inspection Date Oct 2, 1989

Permittee/Operator Name Beaver Creek Coal Company
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine C.V Spur ☐ Surface ☐ Underground ☒ Other
County Carbon State Ut
Company Official(s) Jay Marshal
State Official(s) Bill Malencik
Time of inspection 7:30 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection SEPTEMBER 19, 1989 Weather conditions Clear / Warm / Dry Mine Site
Acreage 160 ☐ Permitted 108 ☐ Disturbed ☐ Regraded ☐ Seeded 108 ☐ Bonded
Enforcement Action None
✓ Followup Item

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☒
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. A/007/022

Inspection Date Oct 2, 1989

Please number comments to correspond with topics on previous page.

General Comments: Dan Guy the operators environmental Coordinator was not available for this inspection. He was on a special assignment to Wyo. Discussed the inspection with mine manager Jay Marshal.

Permit. Recent permit action included the following.

- Permit amendment approved on the runoff & required pond 6 storage capacity. The permit language had a 30 day pond draw down which was designed when the operator washed coal and did not have a discharge permit.
- Operator filed an amendment proposal for a realignment of the haul road. Supervisor (Permit) Smith advised me the permit is in the final stages of approval.

Stream Channel Diversion: Co-Ops two sediment ponds lie ~~north~~ north of the C.V Spur headout and contiguous to C.V Spurs undisturbed ditch. Because of this past summer high intensity storms and the high risk of commingling Co-Op & C.V Spur runoff, the operator is hereby requested to meet with Co-Op officials to develop and reduce to writing

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date Oct 2, 1989

Please number comments to correspond with topics on previous page.

a solution to this potential problem.

Topsoil Seedbed preparation work had been performed on all topsoil areas the previous week.

Sediment Ponds. Sediment ponds 1, 2, & 3 were dry; 5 & 6 contained water. Water was approaching the spillway level on pond 6; two feet below spillway level on pond 5. The operator was requested drawdown the water level in pond 6 in order to maintain required runoff capacity. No visible signs were observed that water had discharged through the spillway. However a small amount of water was observed at the culvert outlet, insufficient to sample, and presumably seeping from the pond.

Other Sediment Control: Several silt fences in one ditch on the southerly portion of the loadout while still functional need to be cleaned.

Revegetation. Revegetation new test plot adjacent to and north of pond 2 & 3 has recently been installed. The plot is fenced.

Road. The new Ridge Road now under construction will change the the entrance/exit. The new segement about 100' in length will enter the loadout on the west side and just S of the office

Copy of report mailed to SLC FOR OSM/Brain Smith; DOGM/Joe Helfrich
Beaver Creek/Dan Guy

Copy of ~~report given~~ filed to PFO (Xerox Copy)

Inspector's signature Wm. J. Malinick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

10/3/89