7035 0005

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

GVS

inspection report

Permit No. ACT/007/022

Inspection Date July 20, 1989 July 25, 1989

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine CV Spur (Choadout) ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) Dan Guy.

State Official(s) Bill Malencik

Time of inspection 7/20/89 10 : 00 ☒ a.m. ☐ p.m. to 3 : 00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
7/25/89 8:00 ☒ 2:00 ☒

Date of last inspection June 22, 1989. Weather conditions Hot/Dry.

Acreage 160 ☐ Permitted 108 ☐ Disturbed ☐ Regraded ☐ Seeded 160 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☒	☐	☐	☒
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/002

Inspection Date July 20, 25, 1989

Please number comments to correspond with topics on previous page.

General Comments: The loadout is operational. No coal is currently being washed. Unless coal prices increase its doubtful that coal washing will be reactivated. The site and records were found in good order.

Permit. The permit expires in August, 1989. Operator applied applied for a permit renewal on April 18, 1989, and renewal efforts appear to be on schedule.

Annual report was submitted to the Division on 3/31/89. Bond and insurance documents were of record and no problems noted.

Diversion. Undisturbed diversions coming into and out of the C.V. Spur loadout were checked and no problems noted. The undisturbed diversions contained a minor amount of runoff, but no erosion problems or short circuiting was noted. No comingling of Co-Op runoff with C.V Spur runoff on the latters North boundary.

Disturbed diversion also showed evidence of runoff. The culvert by the silo was half full of sediment; however, the operator had done work on the inlet.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/002

Inspection Date July 20/25, 1989

Please number comments to correspond with topics on previous page.

The culvert is operation and in spite of the work showed no evidence of topping and/or water accumulation at the inlet.

Sediment Ponds & Impoundment: Ponds 1, 5 & 6 contained water. Ponds 2 & 3 and the thickner impoundment were dry.

Pond inspection by the operator were conducted in C.Y. 89 and dated 3/30/89 and 6/26/89. As built drawings were on file.

At the time of inspection water was being recirculated from the holding cell next to pond 6 to the water storage tank.

Water Monitoring: Water monitoring on 11 stations consisting of wells, ditches and french drain were performed by the operator. No problems detected.

Effluent Limitations: UPDES report submitted on UT-0023949 dated 7/22/89 and no discharge reported.

Non-Coal Waste: Non coal waste dumpster was observed and the site was clean. Oil & Grease is stored

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/002

Inspection Date July 20, 25, 1989

Please number comments to correspond with topics on previous page.

in a surface yellow colored tank below the truck dump turnoff. The tank is estimated to hold about 1000 gallons.

Protection Of Wildlife Et Al The operator stated he would be installing raptor adapters on 4 power poles that lie south of their substation

Roads Roads were well watered at the time of the inspection

Copy of report mailed to SLC: For OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to Beaver Creek Coal Co/Dan Guy.

Inspector's signature Tim J Malinich No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

DOGM/IR-2 7/25/89 an equal opportunity employer 11/86 001049