4-14-
7035

0009

RVS

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022

Inspection Date APRIL 6, 1989

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UT Zip 84501

Mine C.V. SPUR (LOADOUT) ☐ Surface ☐ Underground ☒ Other

County CARBON State UT

Company Official(s) DENNIS MOGENSEN

State Official(s) BILL WAKMACK

Time of inspection 2 00 ☐ a.m. ☒ p.m. to 3 00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last Inspection MARCH 9, 1989 Weather conditions WARM & WINDY

Acreage 160 ☒ Permitted 160 ☒ Disturbed ☐ Regraded ☐ Seeded 160 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 4/6/89

Please number comments to correspond with topics on previous page.

GENERAL: DENNIS MOGENSEN (BCCC) ACCOMPANIED THE UNDERSIGNED ON THIS PARTIAL INSPECTION. THE LOADOUT FACILITY WAS VERY DRY, ESPECIALLY IN THE OPEN FLAT AREAS.

4A. OTHER SEDIMENT CONTROLS: NEW STRAW BALES & SILT FENCES HAVE BEEN INSTALLED AT SEVERAL LOCATIONS:

1) NEW BALES @ POND #6 SPILLWAY
2) NEW BALES BELOW JENSEN TRUCKING
3) NEW BALES & SILT FENCE @ TOPSOIL PILES.

6. DEVELOPMENT WASTE & SPOIL DISPOSAL: THE SNOW & ICE PILE HAS BEEN MOVED & SPREAD OUT ON THE REFUSE PILE TO FACILITATE THAWING.

16. ROAD MAINTENANCE: TO ALLEVIATE DUST, ROADS WERE BEING TREATED WITH WATER.

Copy of report mailed to DAN GUY (BCCC), JOE HELFRICH (DOGM), BRIAN SMITH (OSM)

Copy of report given to PFO

Inspector's signature William A. Warmack 4/10/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE