3-2-89
7035

0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022
Inspection Date FEB. 9, 1989

Permittee/Operator Name BEAVER CREEK COAL CO.
Business Address P.O. BOX 1378
City PRICE State UT Zip 84501
Mine C.V. SPUR (LOADOUT) ☐ Surface ☐ Underground ☒ Other
County CARBON State UT
Company Official(s) DAN GUY
State Official(s) BILL WAKMACK
Time of inspection 1 30 ☐ a.m. ☒ p.m. to 3 00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection JAN. 12, 1989 Weather conditions OVERCAST & COLD
Acreage 160 ☒ Permitted 108 ☒ Disturbed ☐ Regraded ☐ Seeded 160 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☐	☐	☐	☐
d. Other sediment control measures	☐	☐	☐	☐
e. Surface and groundwater monitoring	☒	☐	☐	☒
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☐	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 2/9/89

Please number comments to correspond with topics on previous page.

GENERAL: GROUND CONDITIONS WERE MOIST, SOME MELTING OF THE SNOW & ICE WAS OCCURRING & RUNOFF WAS PROPERLY CONVEYED BY THE SERIES OF DITCHES & CULVERTS.

4b. DIVERSIONS: ALTHOUGH THE DITCHES CONTAIN SOME SNOW & ICE, THEIR CAPACITIES OR FUNCTIONS HAVE NOT BEEN AFFECTED. AS STATED ABOVE, THE SMALL AMOUNT OF SNOW MELT WAS BEING PROPERLY DIRECTED TO THE SEDIMENTATION PONDS.

4c. WATER MONITORING: AT THE TIME THE LAST COMPLETE INSPECTION WAS CONDUCTED (1/12/89), 4th QUARTER RESULTS WERE BEING COMPILED & THEREFORE NOT REVIEWED. HOWEVER, RECORDS WERE REVIEWED DURING THIS PARTIAL & 4th QUARTER RESULTS WERE FOUND COMPLETE.

7. COAL PROCESSING WASTE: THE COAL PROCESSING WASTE PILE WAS INSPECTED & FOUND IN A STABLE, WELL COMPACTED STATE.

Copy of report mailed to DAN GUY (BCCC) FILED TO: PFO

Copy of report given to SLC FOV: JOE HELFRICH (DOGM), BRIAN SMITH (OSM)

Inspector's signature William A. Warmack 2/10/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE