0010

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022
Inspection Date 6/13/90

Permittee/Operator Name Beaver Creek Coal Co.
Business Address P.O. Box 1378
City Price State Ut Zip 84501
Mine C.V Spur loadout ☐ Surface ☐ Underground ☒ Other
County Carbon State Ut
Company Official(s) Dan Guy
State Official(s) Bill Malencik
Time of inspection 8:00 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection 5/3/90 Weather conditions Clear & Warm
Acreage 160 ☐ Permitted 108 ☐ Disturbed ☐ Regraded ☐ Seeded 108 ☐ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 6/13/90

Please number comments to correspond with topics on previous page.

Impoundment. The thickner impoundment previously used in the coal washing operation has, with the concurrence of the Division, been covered. The area will now be utilized as a coal storage contiguous to an existing coal area.

Revegetation. Last fall seeding on the topsoil & subsoil pile shows a general lack of seeded species. Some weeds were observed, but for the most part the soil piles are bare or void of any significant vegetation. The soil piles are protected with a berm and augmented with silt fences and straw bales.

The refuse test plot and the test plot near the pumphouse is likewise nearly void of seeded vegetation.

Road. Roads were in good condition and were watered before and during the inspection as a dust abatement measure.

Other. Coal was stored in the area west of the railroad tracks and south of the silo. Runoff from this area drains across a pad and into a ditch and/or sediment pond.

BCCC: Dan Guy.

Copy of report mailed to SLC: OSM/ Brian Smith, DOGM/Joe Helfrich

Copy of report ~~given to~~ RFO

Inspector's signature Tim J. Malencik No. 26

6/19/90.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE