0015

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022

Inspection Date 1/30/90

Permittee/Operator Name BEAVER CREEK COAL COMPANY

Business Address P.O. BOX 1378

City PRICE State UTAH Zip 84501

Mine C.V. SPUR LOADOUT ☒ Surface ☐ Underground ☐ Other

County CARBON State UTAH

Company Official(s) MEL COONROD

State Official(s) TOM MUNSON

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 5:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 12/21 Weather conditions CLOUDY

Acreage 160 ☒ Permitted 108 ☒ Disturbed ☐ Regraded ☐ Seeded 108 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☒	☐	☐	☐
e Surface and groundwater monitoring	☒	☐	☐	☐
f Effluent limitations	☒	☐	☐	☐
5. Explosives	☒	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 1/30/90

Please number comments to correspond with topics on previous page.

GENERAL COMMENTS A complete inspection was preformed and ~~was~~ no compliance problems were noted during the field inspection or the record review. The items which were observed as not being monitored in the last complete inspection was specific review of the 4th quarter monitoring since it had not been completed at the time of inspection. ~~The~~ Water data was reviewed at the time of this complete inspection and no problems were observed. Any other items addressed in this report will be follow-up items from previous inspections due to the fact no maintenance or compliance items were observed

2. Signs and Markers

The operator has determined that no sign is needed, after consulting with the Division inspector, for the access point to the railroad grade access road

Copy of report mailed to

Copy of report given to

Inspector's signature Tom Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 1/30/90

Please number comments to correspond with topics on previous page.

2) cont. since it is a non-public road and has no access other than through C.V. SPUR.

4 C. The upper pond was cleaned and all material was removed to the refuse pile

13. No results have been received on the seeds so the operator has not submitted the as-built drawings of the vegitation test plot, but will do so as soon as they are received.

Copy of report mailed to OSM / BRIAN SMITH ; DOGM / JOE HELFRICH

Copy of report given to BEAVER CREEK COAL CO. / DAN GUY

Inspector's signature Tom Munson 1/30/90 No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE