0002

get page

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022

Inspection Date 18 December 1991

Permittee/Operator Name Mountain Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine C.V. Spur ☐ Surface ☐ Underground ☒ Other

County Carbon State Utah

Company Official(s) Dan Guy, Bill Biersdorf

State Official(s) Jess Kelley

Time of inspection 12:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 26 November 1991 Weather conditions Cold and cloudy

Acreage 160 ☐ Permitted 108 ☐ Disturbed 0 ☐ Regraded 0 ☐ Seeded 108 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☒
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 18 December 1991

Please number comments to correspond with topics on previous page.

3. TOPSOIL

Topsoil stockpiles have been seeded repeatedly, but contain very little vegetation. Stockpiles are damp and seem to be very stable.

4. HYDROLOGIC BALANCE

(b) Diversions -- Ditches are clean and in good repair. Ditches in vicinity of refuse pile have been reconstructed pursuant to a Division Order (DO-91A).

(c) Sediment Ponds and Impoundments -- Sediment ponds contain some water. Open channel spillways have been installed in both ponds (Division Order DO-91A). Spillways are rip-rapped and in good condition.

6. DEVELOPMENT WASTE AND SPOIL DISPOSAL

Top of refuse pile has been graded to provide positive drainage to ditches. Refuse pile is stable and covered by a sparse vegetation. Regrading has been done pursuant to a Division Order (DO-91B).

Copy of report mailed to Dan Guy / Mountain Coal ; Bernie Freeman / OSM

Copy of report given to Joe Helfrich / DOGM ; Price Field Office / DOGM

Inspector's signature Jesse N. Kelley No. 34

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE