0013

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/022

Inspection Date 26 February 1992

Permittee/Operator Name Mountain Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine C.Y. Spur ☐ Surface ☐ Underground ☒ Other

County Carbon State Utah

Company Official(s) Dan Guy, Bill Biersdorf

State Official(s) Jess Kelley

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 29 January 1992 Weather conditions Sunny and warm

Acreage 160 ☐ Permitted 108 ☐ Disturbed 0 ☐ Regraded 0 ☐ Seeded 108 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 26 February 1992

Please number comments to correspond with topics on previous page.

1. PERMITS

AVS Check: Permittee is listed as
Mountain Coal Company
P.O. Box 1378
Price, Utah 84501

2. SIGNS AND MARKERS

Site ID signs are in place and in good repair, as are perimeter and topsoil markers.

13. REVEGETATION

Test plots on top of coal waste pile are dry, but covered with vegetation. Topsoil stockpiles are almost bare, despite multiple seedings.

16. ROADS

(d) Maintenance -- Roads are well-maintained but dust is becoming a problem. Roads should be watered regularly to control dust.

Copy of report mailed to Dan Guy/Mountain Coal; Bernie Freeman/OSM

Copy of report given to Joe Helfrich/DOGM; Price Field Office/DOGM

Inspector's signature Jesse N. Kelley No. 34

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE