0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. Act 007/022

Inspection Date 2/22/93

Permittee/Operator Name Mountain Coal Co.

Business Address P.O. Box 591

City Somerset State Colo Zip 81434

Mine C.V Spur ☐ Surface ☐ Underground ☒ Other

County Carbon State Ut

Company Official(s) Dan Guy (MCC Representative)

State Official(s) Bill Malencik

Time of inspection 8 : 30 ☐ a.m. ☐ p.m. to 1 : 00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 1/14 & 20/93 Weather conditions Cloudy/Snowed Night Before Insp.

Acreage 160 ☒ Permitted 122 28 ☐ Disturbed ☐ Regraded ☐ Seeded 122 28 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/007/022

Inspection Date 2/22/93

Please number comments to correspond with topics on previous page.

General Comments. Most of the loadout was covered with snow that had fallen the night before. The exception being areas where the snow was removed.

Diversion. A diversion on the north side and at the base of the refuse pile had snow that had been pushed into the ditch. The operator cleaned the ditch in question before the undersigned completed the inspection.

Sediment Ponds. The only sediment pond that contained water was pond 6, it being ice and snow covered. All sediment ponds contained Sediment markers.

Other Sediment Control. Siltfence and straw bales were observed, but judgements on conditions were difficult because of snow cover and the fact no runoff was taking place.

Refuse Pile. The pile was snow covered with the exception of the access road that traversed part of the top of the pile.

Roads. The roads were wet and "sloppy", however no drainage problems were observed on the primary roads.

Copy of report mailed to Ms K Welt/MCC; Brian Smith/OSM; Joe Helfrich/DOGM

Copy of report ~~given to~~ filed RFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

2/24/93