10-26-88 7160

UTAH NATURAL RESOURCES
Oil, Gas & Mining

0011

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gph

inspection report

Permit No. PMO/007/033

Inspection Date 10/14/88

Permittee/~~Operator~~ Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut. Zip 84501

Mine Wildcat Loadout ☐ Surface ☐ Underground ☒ Other

County Carbon State Ut.

Company Official(s) John Pappas

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 9/8/88 Weather conditions Raining/Hailing

Acreage NA ☐ Permitted 60 ☐ Disturbed NA ☐ Regraded 60 ☐ Seeded NA ☐ Bonded

Enforcement Action None

Maintenance Items: Underscored On Attached Pages.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 10/14/88

Please number comments to correspond with topics on previous page.

General Comments: The Wildcat headout during the instant inspection was hit by a rain & hail storm. The site was in good condition with a few maintenance items, not of a nature to constitute a non-compliance issue, but important enough to be pointed out to the operator and documented in this report.

Maintenance items identified in the report of 9/8/88 have been completed.

Diversions. All diversions were field reviewed. The diversion that drains the Beaver Creek Shop area has breech a berm and now flows, as noted in previous reports under the railroad tracks and into an undisturbed drainage adjacent to the Wildcat Scale. The responsibility for maintenance is Beaver Creek Coal Co. However Andalex Resources should take the responsibility to see that repairs are made before the next DOGM inspection.

Copy of report mailed to { SLC. OSM/Brian Smith; DOGM/Joe Helfrich; Andalex Resources; Beaver Creek Coal Co

Copy of report ~~given~~ filed to PFO.

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 10/14/88

Please number comments to correspond with topics on previous page.

Sediment Pond. Sediment pond "C" embankment needs runoff protection in order to avoid embankment erosion near the culvert inlet. None of the ponds contained water.

Coal Processing Waste. Bony is now being stored in an area previously utilize by Savage for coal waste storage.

Copy of report mailed to { SLC - OSM/Brain Smith; DOGM/Joe Helfrich
Andalex Resources
Beaver Creek Coal Co.

Copy of report ~~given~~ filed to PFO

Inspector's signature Wm. J. Malenick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

10/18/88

DOGM/IR-2

an equal opportunity employer

11/86 001049