8-16

0013

607-033

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/033 7160

Inspection Date 9/8/88

Permittee/Operator Name Andalex Resources

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) John Pappas

State Official(s) Bill Warmack Jim Fricke

Time of inspection 10:00 ☐ a.m. ☐ p.m. to 12:00 ☐ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 8/15/88 Weather conditions clear

Acreage ☐ Permitted 60 ☒ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PR0/007/033

Inspection Date 9/8/88

Please number comments to correspond with topics on previous page.

4b.ac All maintenance items in the previous inspection (8/15/88) were inspected. Most items were in compliance. Pond F inlets were still in need of repair. Mr. Pappas committed to the repair work by 9/10/88.

Repair of Pond E inlet is not warranted due to the proposed pond enlargement.

4e. As noted in the 8/15/88 inspection report this site received a substantial amount of rainfall. The operator is in the process of attaining permit approval with DOGM part of this approval requires 1 year of baseline water quantity and quality data collection. The operator has not attempted to collect any data for the past year during ~~pe~~ the permitting process.

Copy of report mailed to John Pappas & Mike Glasson, Andalex

Copy of report given to Brian Smith OSM, Joe Helfrick DOGM

Inspector's signature Jim Fricke No. 22

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE