0025

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ~~A~~ ACT/007/033

Inspection Date 2/24/88

Permittee/Operator Name Andalex Resources Inc.

Business Address P.O. Box 902

City Price State UT Zip 84501

Mine Wildcat Prep Plant ☐ Surface ☐ Underground ☒ Other

County Carbon State UT

Company Official(s) John Papas

State Official(s) Jim Fricke, Bill Malencik, Harold Sandbeck

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 2/18/88 Weather conditions Clear, 45°

Acreage ☐ Permitted 60 ☒ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
d Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 2/24/88

Please number comments to correspond with topics on previous page.

4b. Several diversion ditches were inspected. All disturbed area runoff was being diverted to sediment controls. The operator was maintaining the ditches at the time of the inspection.

4c. Sediment pond inlets were inspected for Ponds A-F. All inlets were stable and functioning in compliance.

16d. The recent warm weather has dried out the haul roads. The operator was advised to treat the road surface for dust control.

Copy of report mailed to Mike Gustasson, (Andalex) Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Jim Trickle No. 22

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE