0005

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RECEIVED
OCT 10 1989
DIVISION OF OIL, GAS & MINING

gdk RUS

inspection report

Permit No. ACT/007/033
Inspection Date OCT. 2, 1989

Permittee/Operator Name ANDALEX RESOURCES, INC.
Business Address P.O. BOX 902
City PRICE State UT Zip 84501
Mine WILDCAT LOADOUT ☐ Surface ☐ Underground ☒ Other
County CARBON State UT
Company Official(s) JOHN PAPPAS
State Official(s) BILL WARMACK & BILL MALENCIK
Time of inspection ___:___ ☐ a.m. ☐ p.m. to ___:___ ☐ a.m. ☐ p.m. ☐ Partial ☐ Complete
Date of last inspection Sept. 11, 1989 Weather conditions
Acreage 100 ☒ Permitted 60 ☒ Disturbed ☐ Regraded ☐ Seeded 60 ☒ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☒	☐	☐	☒
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☒	☐	☐	☐
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a. Construction	☐	☐	☐	☐
b. Drainage controls	☒	☐	☐	☐
c. Surfacing	☐	☐	☐	☐
d. Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No ACT/007/033

Inspection Date OCT. 2, 1989

Please number comments to correspond with topics on previous page.

3 & 4c: RECONSTRUCTION OF POND E IS ALMOST COMPLETE. EXCAVATED SOIL HAS BEEN STOCKPILED ADJACENT TO THE POND & WILL BE BERMED & SEEDED WITHIN THE WEEK. EARTH-WORK APPEARS TO BE COMPLETED AT THIS TIME, HOWEVER, INLETS NEED TO BE REGRADED.

4b DIVERSIONS: DIVERSION DITCHES THROUGHOUT THE SITE HAVE BEEN REGRADED & CLEANED. A BERM HAS BEEN PLACED PARALLEL TO DITCH D-1 (SOUTH OF LUMP COAL) TO FACILITATE DRAINAGE. THE 1/2 ROUND CULVERT INLET TO SED POND D NEEDS TO BE CLEARED OF WEEDS.

13. REVEGETATION: THE FOUR AREA TEST PLOTS HAVE NOT BEEN SEEDED AS OF YET. SEEDBED PREPARATORY WORK IS REQUIRED & WILL BE COORDINATED WITH MR. MIKE GLASSON (ARI).

Copy of report mailed to MIKE GLASSON (ANDALEX RESOURCES) SLC FOR: JOE HELFRICH (DASM), BRIAN SMITH (OSM)

Copy of report given to PFO

Inspector's signature William A. Warnock 10/3/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE