6-6-89
7160

0024

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

RUS

inspection report

Permit No. ~~PRO~~ ACT/007/033

Inspection Date 4/24/89

Permittee/Operator Name Andalex Resources, Inc

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout Facility ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) John Pappas

State Official(s) Bill Malencik

Time of inspection 7:30 ☒ a.m. ☐ p.m. to 2:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection Weather conditions Warm/Clear/no Wind

Acreage ☐ Permitted 60 ☐ Disturbed ☐ Regraded 60 ☐ Seeded ☐ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☒
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☒	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☒
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 4/24/89

Please number comments to correspond with topics on previous page.

[Permit] Operator is in the final stages of securing a DOGM permit. A review of records included the following: BLM/ROW/U-48072, Utah Railway lease, Utah Health/waste water disposal/air quality, insurance policy, and other required records. Reclamation bond has been approved as of 3/3/89.

WDM 5/30/89

[Topsoil]: Topsoil pile adjacent to sediment pond F has been provided additional sediment control. Sixteen new straw bales have been installed to supplement the four outstanding straw bales. No runoff was observed, nor was there any evidence present that any runoff had accumulated and moved in the ditch protecting the topsoil pile.

[Diversions]: Routine work (D 4, 5, 6, 10, 11, 1, 1d, & 18) was completed on the above ditches. Also from the Beaver Shop area, the new realigned ditch is doing its job and no water is now entering Andalex proposed permit area. It should be mentioned that the drainage from the Beaver Creek Shop

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 4/24/89

Please number comments to correspond with topics on previous page.

has historically drained into an undisturbed drainage that exited the proposed permit area at the north end of the property.

Sediment Ponds: None of the ponds contained runoff. All ponds were stable. Pond F belt lining has been replaced ie, lower portion of two inlets with half-round culvert. Pond E according to the proposed permit stipulation is scheduled to be enlarged before July 1989.

Pond certifications are on file. Inspection reports by the operator has been performed and the most recent inspection is dated 4/19/89.

Other Sediment Control: Operator has installed berms on pad areas where runoff could potentially cause rill erosion on outslope areas.

Coal Processing Waste: Bony continues to be stockpiled in area above the tracks on the west end of the property. The runoff from the bony pile is diverted into pond F.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 4/24/89

Please number comments to correspond with topics on previous page.

Wildlife: The operator advised me that he has received permission to remove the two strands of barb wire from his exterior fence. The fence is a combination net & barb wire. The removal is necessary to protect deer from being entangled in the fence

Revegetation: Four vegetation test plots have been flagged on site.

Road: Checked the haul road from both gates. No problems were observed. However, with the new federal regulations on roads, how the short spur, outside the gates, will be handled is an area that may need future attention. The two short spurs about 100' between the permit area/gate and the State Highway are discussed herein as a point of discussion for possible future consideration depending on how the new federal regulations will be incorporated into the Utah regulations.

Copy of report mailed to SLC FOR: OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report given to Andlex Resources, Inc. John Pappas.

Inspector's signature Tim J. Gralenich No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/24/89.