4-14
7160

0028

RUS

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. PRO/007/033

Inspection Date 3/7/89

Permittee/Operator Name ANDALEX Resources, Inc.

Business Address P.O. BOX 902

City PRICE State UTAH Zip 84501

Mine WILDCAT LOADOUT FACILITY ☐ Surface ☐ Underground ☑ Other

County CARBON State UTAH

Company Official(s) BERT JEANSELME, MIKE GLASSON

State Official(s) PAMELA GRUBAUGH-LITTIG, BILL MALENCIK

Time of inspection 12:30 ☐ a.m. ☑ p.m. to 3:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection 2/15-16/89 Weather conditions 45°; cloudy; muddy

Acreage ☐ Permitted 60 ☑ Disturbed ☐ Regraded ☐ Seeded 60 ☑ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☑	☐	☐	☑
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☑	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☐	☐	☐	☐
b – Diversions	☑	☐	☐	☑
c – Sediment ponds and impoundments	☑	☐	☐	☑
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☐	☐	☐	☐
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☑	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PRO/007/033

Inspection Date 3/7/89

Please number comments to correspond with topics on previous page.

1. The performance bond for the Wildcat Loadout Facility was posted March 1, 1989 for $813,795. (Irrevocable Letter of Credit - Pittsburg National Bank - #55412 - FC).

4b. A "belted" ditch by the lump coal storage is showing signs of minor sloughing but is operable and meets the design requirements.

4c. Rills are beginning to be noticeable on the slopes of Pond C but are only 1" in depth.

NOTE: Pond E contained some water

Copy of report mailed to Mike Gleason - Andalex Resources, Brian Smith OSM

Copy of report given to Joe Helfrich DOGM; PFO

Inspector's signature Pamela Grubaugh-Littig No. 20

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer