0003

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/033

Inspection Date 10/24/90

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) John Pappas

State Official(s) Bill Malencik & Steve Demczak

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 9/27/90 Weather conditions Clear/Warm

Acreage 100 ☐ Permitted 60 ☐ Disturbed ☐ Regraded ☐ Seeded 60 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 10/24/90

Please number comments to correspond with topics on previous page.

Permit. The Division approved a change runoff controls. The change involves an undisturbed diversion on the northeast side of the loadout and a permanent impoundment. The operator has not started to implement this change. Mr. Pappas stated it would be completed this fall.

Sediment Ponds. Sediment ponds were dry, stable, and had adequate sediment capacity. Sediment pond B it would appear may have to be cleaned next year. Since the pond is dry the operator may elect to clean it this fall.

Revegetation. The topsoil piles that must be seeded this fall was discussed with Mr. Pappas. He stated that they would do this prosect this fall. Further, he requested Susan White to be onsite if at all possible during the operation or at least when the job is started. Suggested he coordinate his request with Susan. However, I in turn would alert Susan.

Copy of report mailed to Andalex Resources, Inc / Mike Glasson
OSM / Brian Smith

Copy of report given to DOGM / Joe Helfrich

PFO
Inspector's signature Tim J. Trulenich No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

10/31/90.

DOGM/IR-2 an equal opportunity employer 11/86 001049