0016

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Jd page

inspection report

Permit No. ACT/007/033

Inspection Date May 29, 1990

Permittee/Operator Name Andalex Resources, Inc.

Business Address P.O. Box 902

City Price State Ut Zip 84501

Mine Wildcat Loadout ☐ Surface ☐ Underground ☒ Other

County Carbon State

Company Official(s) John Pappas & Bert Jeanselme

State Official(s) Bill Malencik

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 4/3/90 Weather conditions Cloudy/Cool/Wet Site

Acreage 100 ☐ Permitted 60 ☐ Disturbed ☐ Regraded ☐ Seeded 60 ☐ Bonded

Enforcement Action None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☒
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 5/29/90

Please number comments to correspond with topics on previous page.

General Comments: The loadout had received a general rain the night before the inspection. No runoff was noted, however, part of the site was muddy. The rain gauge measured 0.10" of moisture.

Topsoil: As noted in the previous inspection some grass was observed on the topsoil piles seeded last fall. The topsoil pile next to pond E was nearly void of grass seedlings. Weed competition seems to be inimical to the longevity of the grass seedlings. Some of the leaves are showing evidence of moisture stress.

Sediment Ponds: All six ponds were stable and dry.

Diversions: The operator recently had graded most of the ditches including cleaning weeds out of the ditches. The undisturbed ditch cut several years ago in the NW segement of the loadout needs continual surveillance. The disturbed area associated with the ditch had been seeded and cover is poor. Some grass and winter fat has been established.

Revegetation: The vegetation test plots were checked. Weeds have taken over the plots.

Copy of report mailed to ARI/Mike Glasson; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ PFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

5/30/90

DOGM/IR-2

an equal opportunity employer

11/86 001049