0018

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/007/033

Inspection Date 1/18/91

Permittee/Operator Name ANDALEX RESOURCES, INC.

Business Address P.O. BOX 902

City PRICE State UTAH Zip 84501

Mine WILDCAT LOADOUT ☐ Surface ☐ Underground ☒ Other

County CARBON State UTAH

Company Official(s) JOHN PAPPAS

State Official(s) ~~[illegible]~~ TOM MUNSON

Time of inspection 9:00 ☒ a.m. ☐ p.m. to 10:30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 12/27/90 Weather conditions FAIR AND COLD

Acreage 100 ☐ Permitted 60 ☐ Disturbed ☐ Regraded ☐ Seeded 60 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	✓			
2. Signs and markers				
3. Topsoil	✓			✓
4. Hydrologic balance				
— Stream channel diversions				
D Diversions	✓			✓
C Sediment ponds and impoundments	✓			✓
— Other sediment control measures				
— Surface and groundwater monitoring				
— Effluent limitations				
5. Explosives				
6. Development waste and spoil disposal				
7. Coal processing waste				
8. Noncoal waste				
9. Protection of fish, wildlife, and related environmental values				
10. Slides and other damage				
11. Contemporaneous reclamation				
12. Backfilling and grading				
13. Revegetation				
14. Subsidence control				
15. Cessation of operations				
16. Roads				
— Construction				
— Drainage controls				
— Surfacing				
— Maintenance				
17. Other transportation facilities				
18. Support facilities and utility installations				

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/033

Inspection Date 1/18/91

Please number comments to correspond with topics on previous page.

3. TOPSOIL - TOPSILE PILES HAVE BEEN MULCHED AS REQUESTED.

4 b. Culverts and Diversions - They were clear and frozen due to the winter conditions

c. Sediment ponds and impoundments - The ponds were clear and contained no water. The permanent impoundment improvements have not been initiated to date due to frozen conditions.

The site was well maintained and there was no evidence of runoff due to ~~the~~ frozen conditions.

Copy of report mailed to Mike Blasson / Andalex; John Kathman / OSM

Copy of report given to JOE HELFRICH

Inspector's signature Tom Munson No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE