0011

A 007/033 #2
92C

ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (801) 637-5385
TELECOPIER (801) 637-8860

March 26, 1992

RECEIVED
MAR 31 1992
DIVISION OF
OIL GAS & MINING

State of Utah
Department of Natural Resources
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Attn: Pamela Grubaugh-Littig
re: Minor Modification, ACT 007/033

Dear Ms. Littig:

Enclosed are 4 copies each of revised plate 2 "Surface Facilities Topography, Watershed and Drainage". The revision depicts a 12" half round culvert in place on the eastern edge of Small Area Exemption #1. This culvert is recommended because of the fact that water does not effectively drain from this portion of the SAE and it is possible that the berm in place on the eastern edge of the SAE could be breached. This half round will effectively drain this small area which runs along the edge of the berm. The acreage involved is negligible and as such, the affect on the already oversize pond E is also negligible.

Also enclosed are copies of revised page 128 for insertion into the MRP. This page, which formerly described the use of an approved "landfill" for disposal of silt, now states an approved "refuse disposal area" will be used.

Also enclosed are copies of revised pages 109,107 and 105; tables IV-7, IV-6 and IV-5 which formerly showed Pond E as "proposed" which now shows the pond as "existing".

Finally, I have enclosed information, including the most recent inspection report indicating that Andalex's air quality approval order covers both the mines and the loadout.

Please call with questions.

Sincerely,

Michael W. Glasson
Senior Geologist

MWG/jo

Enclosures