0003

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial:__ Complete: XXX Exploration:__
Inspection Date & Time: 10/4/96 / 7:00a.m.-12:00p.m.
Date of Last Inspection: 9/4/96

Mine Name: Wildcat Loadout County: Carbon Permit Number: **ACT/007/033**
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P. O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground__ Surface__ Prep. Plant XXX Other__
Company Official(s): John Pappas
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Clear, 70's
Existing Acreage: Permitted-100 Disturbed-63.7 Regraded-_ Seeded-_ Bonded-60
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: _Exploration/ XXX Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2.	SIGNS AND MARKERS	[XX]	[ ]	[ ]	[ ]
3.	TOPSOIL	[XX]	[ ]	[ ]	[ ]
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
c.	OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[XX]	[ ]
d.	WATER MONITORING	[XX]	[ ]	[ ]	[ ]
e.	EFFLUENT LIMITATIONS	[XX]	[ ]	[ ]	[ ]
5.	EXPLOSIVES	[ ]	[XX]	[ ]	[ ]
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	[ ]	[ ]	[ ]
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
8.	NONCOAL WASTE	[XX]	[ ]	[XX]	[ ]
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[XX]	[ ]	[ ]	[ ]
10.	SLIDES AND OTHER DAMAGE	[XX]	[ ]	[ ]	[ ]
11.	CONTEMPORANEOUS RECLAMATION	[XX]	[ ]	[ ]	[ ]
12.	BACKFILLING AND GRADING	[XX]	[ ]	[ ]	[ ]
13.	REVEGETATION	[XX]	[ ]	[ ]	[ ]
14.	SUBSIDENCE CONTROL	[XX]	[ ]	[ ]	[ ]
15.	CESSATION OF OPERATIONS	[ ]	[XX]	[ ]	[ ]
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[ ]	[ ]	[ ]
b.	DRAINAGE CONTROLS	[XX]	[ ]	[ ]	[ ]
17.	OTHER TRANSPORTATION FACILITIES	[XX]	[ ]	[ ]	[ ]
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	[ ]	[ ]	[ ]
19.	AVS CHECK (4th Quarter-April, May, June)_____(date)	[XX]	[ ]	[ ]	[ ]
20.	AIR QUALITY PERMIT	[XX]	[ ]	[ ]	[ ]
21.	BONDING & INSURANCE	[XX]	[ ]	[ ]	[ ]

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: **ACT/007/033** DATE OF INSPECTION: 10/4/96

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

a) The water monitioring report for second quarter showed no water flows. There have not been any water samples taken from this site in years.

b) The sediment ponds inspections were taken on September 26, 1996. There were no reports of any hazardous conditions.

c) The refuse pile inspection for third quarter was taken on September 26, 1996. The inspection report did not indicate any hazardous condition being reported.

d) The insurance acord form was inspected and complies with the R645 regulations. This policy will expire on July 1, 1997.

4A. DIVERSIONS -

The diversions were inspected with minor maintenance needed. The permittee has committed to clean-up the sediment within the ditches. All ditches were functioning as designed.

4B. SEDIMENT PONDS -

The sediment ponds were inspected with no signs of hazardous conditions occuring. There were no signs of erosion to inlets or outlets of the sediment ponds. These ponds were inspected as required by the regulations.

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: **ACT/007/033**

DATE OF INSPECTION: 10/4/96

(Comments are Numbered to Correspond with Topics Listed Above)

4C. OTHER SEDIMENT CONTROL MEASURES -

The Wildcat Loadout uses straw bales as its alternate sediment control measures. These ASCA areas were inspected and comply with the requirements in the regulations.

7. NONCOAL WASTE -

Noncoal waste was being properly stored for disposal.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Andalex Resources, Inc. Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: October 23, 1996

Inspector's Signature: #39
Stephen J. Demczak