0006

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial:__ Complete: XXX Exploration:__
Inspection Date & Time: 7/11/96 / 8:00a.m.-1:00p.m.
Date of Last Inspection: 6/6/96

Mine Name: Wildcat Loadout County: Carbon Permit Number: **ACT/007/033**
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P. O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground__ Surface__ Prep. Plant XXX Other__
Company Official(s): Johnny Pappas
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Hot, 90's
Existing Acreage: Permitted- 100 Disturbed- 63.7 Regraded-_ Seeded-_ Bonded- 60
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: _Exploration/ XXX Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2.	SIGNS AND MARKERS	[XX]	[ ]	[ ]	[ ]
3.	TOPSOIL	[XX]	[ ]	[XX]	[ ]
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
c.	OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[XX]	[ ]
d.	WATER MONITORING	[XX]	[ ]	[ ]	[ ]
e.	EFFLUENT LIMITATIONS	[XX]	[ ]	[ ]	[ ]
5.	EXPLOSIVES	[ ]	[XX]	[ ]	[ ]
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	[ ]	[ ]	[ ]
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
8.	NONCOAL WASTE	[XX]	[ ]	[ ]	[ ]
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[XX]	[ ]	[ ]	[ ]
10.	SLIDES AND OTHER DAMAGE	[XX]	[ ]	[ ]	[ ]
11.	CONTEMPORANEOUS RECLAMATION	[XX]	[ ]	[ ]	[ ]
12.	BACKFILLING AND GRADING	[XX]	[ ]	[ ]	[ ]
13.	REVEGETATION	[XX]	[ ]	[ ]	[ ]
14.	SUBSIDENCE CONTROL	[ ]	[XX]	[ ]	[ ]
15.	CESSATION OF OPERATIONS	[XX]	[ ]	[ ]	[ ]
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[ ]	[ ]	[ ]
b.	DRAINAGE CONTROLS	[XX]	[ ]	[ ]	[ ]
17.	OTHER TRANSPORTATION FACILITIES	[XX]	[ ]	[ ]	[ ]
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	[ ]	[ ]	[ ]
19.	AVS CHECK (4th Quarter-April, May, June)_____(date)	[XX]	[ ]	[XX]	[ ]
20.	AIR QUALITY PERMIT	[XX]	[ ]	[ ]	[ ]
21.	BONDING & INSURANCE	[XX]	[ ]	[ ]	[ ]

PERMIT NUMBER: **ACT/007/033** DATE OF INSPECTION: 7/11/96

(Comments are Numbered to Correspond with Topics Listed Above)

1) PERMIT -

a) The water monitoring for second quarter showed no flow at any of the locations. This was taken on June 30, 1996.

b) The NPDES self sampling of sediment ponds for second quarter were not discharging. The ponds were dry during the inspection. It is highly unlikely a discharge will occur in the near future.

c) The refuse pile was P.E. certified on June 24, 1996. There were no hazardous conditions being reported.

d) The insurance acord form was renewed on July 1, 1996. This policy meets the requirements of the R645 regulations.

e) The sediment ponds were inspected for second quarter and there were no hazardous conditions reported.

3. TOPSOIL -

The topsoil piles were inspected and there were no signs of erosion of the soil. Some vegetation has been established but the site does not receive much rainfall. The topsoil piles are protected by berms.

4A. DIVERSIONS -

The diversions were being cleaned out during and prior to the inspection. The permittee has plans to clean the majority of the diversion. Some ditches did have sediment build-up.

4B. OTHER SEDIMENT CONTROL AREAS -

The alternate sediment control for Wildcat is straw bales. The asca areas were spot-checked and were functioning as designed in the MRP.

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: **ACT/007/033**

DATE OF INSPECTION: 7/11/96

(Comments are Numbered to Correspond with Topics Listed Above)

4C. SEDIMENT PONDS -

The sediment ponds were dry. There were no signs of erosion to the inlet, outlets or embankments. The permittee has submitted new As-built after the clean out of sediment ponds B and D.

19) AVS -

The identification signs reflect the correct information required in the R645 regulations. The signs are located on roads to public access.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Andalex Resources, Inc. Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: July 25, 1996

Inspector's Signature: Stephen J. Demczak #39
Stephen J. Demczak