GARY R. HERBERT
*Governor*
GREG BELL
*Lieutenant Governor*

# State of Utah
DEPARTMENT OF NATURAL RESOURCES
MICHAEL R. STYLER
*Executive Director*
Division of Oil, Gas and Mining
JOHN R. BAZA
*Division Director*

# Inspection Report

| Permit Number: | C0070033 |
|---|---|
| Inspection Type: | PARTIAL OVERSITE |
| Inspection Date: | Wednesday, October 12, 2016 |
| Start Date/Time: | 10/12/2016 11:00:00 AM |
| End Date/Time: | 10/12/2016 4:00:00 PM |
| Last Inspection: | Thursday, September 15, 2016 |

Inspector: Steve Demczak,

Weather: Sunny, 60's

InspectionID Report Number: 5670

Accepted by: DHADDOCK
10/25/2016

| Representatives Present During the Inspection: | |
|---|---|
| Company | Karin Madsen |
| OSM | Duane Matt |
| OGM | Steve Demczak |

Permitee: **INTERMOUNTAIN POWER AGENCY**
Operator: **WILD WEST EQUIPMENT & HAULING, LLC**
Site: **WILDCAT LOADOUT**
Address: **PO BOX 1, PRICE UT 84501**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **INACTIVE**

**Current Acreages**

| | |
|---|---|
| 111.62 | **Total Permitted** |
| 111.62 | **Total Disturbed** |
| | **Phase I** |
| | **Phase II** |
| | **Phase III** |

**Mineral Ownership**

- [x] **Federal**
- [ ] **State**
- [ ] **County**
- [ ] **Fee**
- [ ] **Other**

**Types of Operations**

- [ ] **Underground**
- [ ] **Surface**
- [x] **Loadout**
- [x] **Processing**
- [ ] **Reprocessing**

**Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:**

This was a partial oversite at Wildcat with OSM inspector Duane Matt.

The loadout was idle at the time of the inspection. Coal has not been loaded out at this site for several months. No coal is currently stockpile at the site.

The oil loading facility is currently idle.

Stephen J. Demczak

**Inspector's Signature:**

**Date** Monday, October 24, 2016

Steve Demczak,
Inspector ID Number: 39

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

***REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS***

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

| | Evaluated | Not Applicable | Comment | Enforcement |
|---|---|---|---|---|
| 1. Permits, Change, Transfer, Renewal, Sale | ☑ | ☐ | ☑ | ☐ |
| 2. Signs and Markers | ☑ | ☐ | ☑ | ☐ |
| 3. Topsoil | ☑ | ☐ | ☑ | ☐ |
| 4.a Hydrologic Balance: Diversions | ☑ | ☐ | ☑ | ☐ |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | ☑ | ☐ | ☑ | ☐ |
| 4.c Hydrologic Balance: Other Sediment Control Measures | ☑ | ☐ | ☑ | ☐ |
| 4.d Hydrologic Balance: Water Monitoring | ☐ | ☐ | ☐ | ☐ |
| 4.e Hydrologic Balance: Effluent Limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Disposal of Excess Spoil, Fills, Benches | ☐ | ☐ | ☐ | ☐ |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | ☑ | ☐ | ☑ | ☐ |
| 8. Noncoal Waste | ☑ | ☐ | ☑ | ☐ |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and Other Damage | ☑ | ☐ | ☑ | ☐ |
| 11. Contemporaneous Reclamation | ☐ | ☐ | ☐ | ☐ |
| 12. Backfilling And Grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☐ | ☐ | ☐ | ☐ |
| 14. Subsidence Control | ☐ | ☐ | ☐ | ☐ |
| 15. Cessation of Operations | ☐ | ☐ | ☐ | ☐ |
| 16.a Roads: Construction, Maintenance, Surfacing | ☐ | ☐ | ☐ | ☐ |
| 16.b Roads: Drainage Controls | ☑ | ☐ | ☑ | ☐ |
| 17. Other Transportation Facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support Facilities, Utility Installations | ☐ | ☐ | ☐ | ☐ |
| 19. AVS Check | ☐ | ☐ | ☐ | ☐ |
| 20. Air Quality Permit | ☐ | ☐ | ☐ | ☐ |
| 21. Bonding and Insurance | ☐ | ☐ | ☐ | ☐ |
| 22. Other | ☐ | ☐ | ☐ | ☐ |

**1. Permits, Change, Transfer, Renewal, Sale**

Currently there are no amendments with the Division. A mid-term review will be schedule in the near future.

**2. Signs and Markers**

The identifications sign at the main gate to the property was inspected and meets the requirements of the R645 Coal Rules. See Picture

**3. Topsoil**

The topsoil piles are protected by berms. I did not see any signs of water or wind erosion.

**4.a Hydrologic Balance: Diversions**

The diversions and culverts on the coal side of the tracks were recently cleaned out. The oil loading side of the property needed maintenance. Sediment has started to fill the diversions and culverts. This was due to a recent rainstorm. It was reported by the Price City newspaper that the storm was a 1,000 year storm. The permittee has plans to clean this section of the property.

**4.b Hydrologic Balance: Sediment Ponds and Impoundments**

Most sediment ponds did contain water but were not discharging. Some erosion work is needed to the upper sediment pond on the oil side of the property. The storm water over topped the culvert and road and entered the pond causing some erosion. Permittee will repair the in-slope of the pond.

**4.c Hydrologic Balance: Other Sediment Control Measures**

Sediment stayed on site after the recent rain storm. I did not see any evidence that sediment left the disturbed area.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

I inspected the refuse area and no hazardous conditions were noticed. Slopes appear to be stable.

**8. Noncoal Waste**

The loadout was clear of non-coal waste material.

**10. Slides and Other Damage**

No slides or other damage was noticed during the inspection.

**16.b Roads: Drainage Controls**

Road drainage was functioning as designed. Diversions and culverts were open.

SPEED
LIMIT
5
SURVILLANCE CAMERAS IN USE
ATTENTION
SIGN IN AT SCALE HOUSE PRIOR TO PROCEEDING ONTO PROPERTY
NOT
WITHOUT PRIOR
DELIVERIES, VEN
AND JOB APP
CHECK IN AT
LOCATED A
WILDCAT LOAD OUT
OWNER: INTERMOUNTAIN POWER AGENCY
P.O. BOX 51111 - ROOM 1263
LOS ANGELES, CALIFORNIA 90051
PHONE: 213-367-0289
UDOGM PERMIT NO. C/007/033
OPERATOR:
WILD WEST EQUIPMENT & HAULING, LLC
P.O. BOX 1
PRICE, UTAH 84501
PHONE: 435-472-3988
MSHA ID NO. 42-01864

TOP SOIL
STORAGE AREA