State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Inspection Report

Permit Number:	**C0070033**
Inspection Type:	PARTIAL
Inspection Date:	Thursday, October 26, 2017
Start Date/Time:	10/26/2017 10:30:00 AM
End Date/Time:	10/26/2017 2:00:00 PM
Last Inspection:	Thursday, September 21, 2017

Inspector: Steve Demczak,

Weather: Sunny, 60's,

InspectionID Report Number: 5990

Accepted by: DHADDOCK
11/7/2017

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Steve Demczak

Permitee: **INTERMOUNTAIN POWER AGENCY**
Operator: **WILD WEST EQUIPMENT & HAULING, LLC**
Site: **WILDCAT LOADOUT**
Address: **PO BOX 1, PRICE UT 84501**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **INACTIVE**

Current Acreages

111.62	**Total Permitted**
111.62	**Total Disturbed**
	Phase I
	Phase II
	Phase III

Mineral Ownership

- [x] Federal
- [ ] State
- [ ] County
- [ ] Fee
- [ ] Other

Types of Operations

- [ ] Underground
- [ ] Surface
- [x] Loadout
- [x] Processing
- [ ] Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Wildcat Loadout was vandalized since the last inspection. Copper wiring was stripped out of conduit and electrical equipment. It is estimated the cost of one million dollars to repair equipment and make the facility operational.

Stephen J. Demczak

Inspector's Signature:

Date Tuesday, October 31, 2017

Steve Demczak,
Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

UTAH DNR OIL, GAS & MINING

Permit Number: C0070033
Inspection Type: PARTIAL
Inspection Date: Thursday, October 26, 2017

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☑	☐	☑	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☑	☐	☑	☐
4.a Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☑	☐	☑	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☐	☐	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☑	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☑	☐	☑	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☑	☐	☑	☐
16.b Roads: Drainage Controls	☑	☐	☑	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

1. Permits, Change, Transfer, Renewal, Sale

There is one permitting action with the Division at this time. It is the "Wildcat Midterm Response". It is scheduled to be reviewed by Division on October 6th.

2. Signs and Markers

The identification sign was inspected and it meets the requirements of the R645 Coal Rules. See Photo

3. Topsoil

I inspected the topsoil piles and I did not see any signs of wind or water erosion. The topsoil piles appear to be stable and protected by a berm. See Photo

4.a Hydrologic Balance: Diversions

The diversions and culverts were open and functioning as designed. Sediment has started to fill within these structures. The permittee had cleaned out several diversions since the last inspection. See Photos

4.b Hydrologic Balance: Sediment Ponds and Impoundments

I inspected the sediment ponds throughout the property. They contained some water but were not discharging. It is unlikely these structures will discharge in the near future. The embankments appear to be stable. Inlets and outlets would function as designed. I did not see any hazardous conditions to these structures.

7. Coal Mine Waste, Refuse Piles, Impoundments

I inspected the refuse pile and it appears to be stable. I did not notice any hazardous conditions to the embankments. The refuse pile has been inactive for several years. See Photos

8. Noncoal Waste

The property was clear of non-coal waste materials such as oil, trash and grease cans.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection. The Loadout appears to be stable.

16.a Roads: Construction, Maintenance, Surfacing

The roads were compacted with no dust control problem.

16.b Roads: Drainage Controls

I inspected the road diversions and culverts throughout the property. They were functioning as designed. See Photos

SPEED
LIMIT
5
WILDCAT LOAD OUT
ATTENTION
SIGN IN AT
SCALE HOUSE
PRIOR TO
PROCEEDING
ONTO PROPERTY
NOTICE
WITHOUT PRIOR APPOINTMENT
DELIVERIES, VENDORS, VISITORS,
AND JOB APPLICANTS MUST
CHECK IN AT MAIN OFFICE
LOCATED AT MINE SITE.

TOP SOIL
STORAGE
TOP SOIL
STORAGE