0002

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

007/034#5

inspection report

Permit No. PR0/007/034

Inspection Date 11-24-87

Permittee/Operator Name Soldier Creek Coal Co.

Business Address PO Box I

City Price State Utah Zip 84501

Mine Banning Siding Prep Plant ☐ Surface ☐ Underground ☑ Other

County Carbon State Utah

Company Official(s) Chris Allen

State Official(s) Holland Shepherd

Time of inspection 12:36 ☐ a.m. ☑ p.m. to 1:15 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection 10-27-87 Weather conditions Sunny - cool

Acreage N/A ~~☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☑ Bonded~~

Enforcement Action none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☑	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☑	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☑	☐	☐	☑
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. PR0/007/034

Inspection Date 11-24-87

Please number comments to correspond with topics on previous page.

4. d. Other Sediment Control Measures:

1. The berm and ditch along the western fenceline is functioning adequately. In some areas the ditch has silted in causing a shallowing of the drainage course. I indicated to the operator that a regrading of the ditch would be needed.

2. I indicated in the October Inspection Report for Banning, that some strawbale dikes had been disrupted by cattle grazing. The dikes have ~~now~~ been replaced by silt fences which have been well constructed, and placed to treat any drainage leaving the site at the south end. Mr. Allen indicated that he would drop the center portion of each dike to prevent the possibility of short circuiting around the ends. The siltfences were installed on Oct. 28 1987.

Copy of report mailed to Chris Allen (SCCC), Brian Smith (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature [signature] 11-24-87 No. #9

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE