0012

RE 4-2-87

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File SCL

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 3-18-87
2:00 to 3:00 p.m.

Permittee and/or Operators Name: Soldier Creek Coal Company
Business Address: P.O. Box I Price, Utah 84501
Mine Name: Banning Siding Permit Number: PRO/007/034
Type of Mining Activity: Underground ___ Surface ___ Other Prepration Plant
County: Carbon
Company Official (s): Chris Allan not present
State Official(s): Holland Shepherd, Bill Malencik
Partial: ___ Complete: X Date of Last Inspection: 2-18-87
Weather Conditions: cloudy, cool, slight runoff
Acreage: Permitted n/a Disturbed n/a Regraded 0 Seeded 0 Bonded 0
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	( )	( )	(X)	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	(X)	( )
f. EFFLUENT LIMITATIONS	( )	( )	(X)	( )
5. EXPLOSIVES	( )	( )	(X)	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	(X)	( )
7. COAL PROCESSING WASTE	(X)	( )	( )	( )
8. NONCOAL WASTE	(X)	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(X)	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	(X)	( )
12. BACKFILLING AND GRADING	( )	( )	(X)	( )
13. REVEGETATION	( )	( )	(X)	( )
14. SUBSIDENCE CONTROL	( )	( )	(X)	( )
15. CESSATION OF OPERATIONS	( )	( )	(X)	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	(x)	( )
b. DRAINAGE CONTROLS	(X)	( )	( )	( )
c. SURFACING	(X)	( )	( )	( )
d. MAINTENANCE	(X)	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	(X)	( )	( )	( )
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	(X)	( )	( )	( )

INSPECTION REPORT
(continuation sheet)

PERMIT NUMBER PRO/007/034 DATE OF INSPECTION 3-18-87

(Comments are Numbered to Correspond with Topics Listed Above)

4. Sediment Ponds and Impoundments:

As a result of heavy storms which passed through the area over the weekend, water in the operator's sediment pond (sediment impoundment) nearly topped the berm surronding it. The operator should heighten the embankments surrounding this structure to prevent overflow during the interim before an approved pond is installed.

Copy of this Report:
Mailed to: Chris Allen, Donna Griffin
Given to: Joe Helfrich, Bill Malencik

Inspectors Signature and Number: Holland Shepherd #9 Date: 3-18-87