0024

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gph SCL

inspection report

Permit No. ACT/007/034

Inspection Date 2-25-88

Permittee/Operator Name Soldier Creek Coal Co.

Business Address PO Box I

City Price State Utah Zip 84501

Mine Banning Siding Prep Plant ☐ Surface ☐ Underground ☑ Other

County Carbon State Utah

Company Official(s) Chris Allen, Boyd Rhodes

State Official(s) Holland Shepherd, Daron Haddock

Time of inspection 2:30 ☐ a.m. ☑ p.m. to 3:30 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete

Date of last inspection 1-25-88 Weather conditions sunny, warm, snow melting

Acreage ☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded

Enforcement Action none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☑	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☑	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☑	☐	☐	☑
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/007/034

Inspection Date 2-25-88

Please number comments to correspond with topics on previous page.

General Comments:

Due to several days of warm temperatures, most of the snow on site, has melted. The resulting runoff has caused some ponding in several locations on the site, but no non compliance situations. Drainage controls during this inspection were functioning adequately.

16. b. Road Drainage:

The operator indicated to me that a large plug of debris will be removed from the ditch servicing the southern most road culvert. The plug is located some 5-6 feet from the culvert outlet and is pushed up against a fence spanning the ditch. The ditch was functioning at the time of inspection.

Copy of report mailed to Chris Allen (Soldier Creek) Brian Smith (OSM)

Copy of report given to Joe Helfrich, Dorm Haddock

Inspector's signature [signature] #9 2-26-88 No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE