0001

STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining
3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340

inspection report

☑ Partial
☐ Complete
☐ Exploration

Inspection Date: December 5, 1995
Time: 8 :00 ☑am ☐pm to 1 :00 ☐am ☑pm
Date of Last Inspection: 11/9/95

Mine Name: Sunnyside Refuse County: Carbon Permit Number: Act 007/035
Permittee and/or Operator's Name: Sunnyside Cogeneration Association
Business Address: PO Box 10, East Carbon, UT 84520
Type of Mining Activity: ☐ Underground ☑ Surface ☐ Prep. Plant ☐ Other
State Officials(s): Bill Malencik
Company Official(s): Jim Comas, Russ Miller
Federal Official(s): N/A
Weather Conditions: Clear / Temp 40's
Existing Acreage: Permitted- 310 Disturbed- 202 Regraded-____ Seeded-____ Bonded- 202
Increased/Decreased: Permitted-____ Disturbed-____ Regraded-____ Seeded-____ Bonded-____
Status: ☐ Exploration / ☑ Active / ☐ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture
☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	☑	☐	☑	☐
2. SIGNS AND MARKERS	☑	☐	☑	☐
3. TOPSOIL	☑	☐	☐	☐
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	☑	☐	☐	☐
b. SEDIMENT PONDS AND IMPOUNDMENTS	☑	☐	☐	☐
c. OTHER SEDIMENT CONTROL MEASURES	☑	☐	☑	☐
d. WATER MONITORING	☐	☐	☐	☐
e. EFFLUENT LIMITATIONS	☐	☐	☐	☐
5. EXPLOSIVES	☐	☐	☐	☐
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	☐	☐	☐	☐
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	☐	☐	☐	☐
8. NONCOAL WASTE	☐	☐	☐	☐
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	☐	☐	☐	☐
10. SLIDES AND OTHER DAMAGE	☐	☐	☐	☐
11. CONTEMPORANEOUS RECLAMATION	☐	☐	☐	☐
12. BACKFILLING AND GRADING	☐	☐	☐	☐
13. REVEGETATION	☐	☐	☐	☐
14. SUBSIDENCE CONTROL	☐	☐	☐	☐
15. CESSATION OF OPERATIONS	☐	☐	☐	☐
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	☐	☐	☐	☐
b. DRAINAGE CONTROLS	☐	☐	☐	☐
17. OTHER TRANSPORTATION FACILITIES	☐	☐	☐	☐
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	☐	☐	☐	☐
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	☐	☐	☐	☐
20. AIR QUALITY PERMIT	☑	☐	☑	☐
21. BONDING & INSURANCE	☐	☐	☐	☐

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/035

Inspection Date 12/5/95

Please number comments to correspond with topics on previous page.

General Comments A partial inspection was completed on the Sunnyside Refuse Pile mining operation. The permittee removed the bulk of the coal fines from the area adjacent to Slurry cell #2. The area has not been totally cleaned and requires some follow measures before the area, if no longer needed, can be ready for reclamation.

Signs & Markers New markers have been installed on all topsoil piles. Duplicated disturbed markers have been removed from the upper mine site. Some remain on the lower site. The regulations provides that disturbed markers must be of uniform design. The confusion existed on the interfacing disturbed markers between the two adjoining permittees having a common boundary.

Other Sediment Control. Discussed the silt fences on the coarse refuse reclaimed haul road. The silt fences were installed as a followup to the acid/toxic road violation and required sediment control for the reclaimed outslope. In those areas where matting was installed, the Division

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/035

Inspection Date 12/5/95

Please number comments to correspond with topics on previous page.

concluded the siltfences should be retained until they reach a stage of deterioration. Immediately thereafter they would be removed since matting and vegetation would provide the necessary treatment

Air Quality The operator was installing siltfences to control coal fines from the coal processing area. It appears that the installation was of poor quality. Advised the operator since the project was not completed, would evaluate the matter at the January inspection

Copy of report mailed to Co-Gen/D. Mattingly; OSM/M Petta; DOGM/J Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature Tim J Drabinski No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE OPERATOR GOLDENROD – NOV FILE

DOGM IR-2 1/2/96.

an equal opportunity employer

11 86 001049