0007

STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining
3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340

inspection report

☑ Partial
☐ Complete
☐ Exploration

Inspection Date: Oct 12, 1995
Time: 8 : 00 ☑am ☐pm to 1 : 30 ☐am ☑pm
Date of Last Inspection: 9/14/95

Mine Name: Sunnyside Refuse County: Carbon. Permit Number: Act 007/035
Permittee and/or Operator's Name: Sunnyside Cogeneration Association
Business Address: P.O. Box 10, East Carbon, Ut. 84520
Type of Mining Activity: ☐ Underground ☑ Surface ☐ Prep. Plant ☐ Other
State Officials(s): Bill Malencik
Company Official(s): None
Federal Official(s): N/A
Weather Conditions: Pt. Cloudy / Temp 60°.
Existing Acreage: Permitted-310 Disturbed-202 Regraded-_____ Seeded-_____ Bonded-202
Increased/Decreased: Permitted-_____ Disturbed-_____ Regraded-_____ Seeded-_____ Bonded-_____
Status: ☐ Exploration / ☐ Active / ☐ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture
☐ Reclamation (☐ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	☐	☐	☐	☐
2. SIGNS AND MARKERS	☐	☐	☐	☐
3. TOPSOIL	☐	☐	☐	☐
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	☑	☐	☑	☐
b. SEDIMENT PONDS AND IMPOUNDMENTS	☑	☐	☑	☐
c. OTHER SEDIMENT CONTROL MEASURES	☐	☐	☐	☐
d. WATER MONITORING	☐	☐	☐	☐
e. EFFLUENT LIMITATIONS	☐	☑	☐	☐
5. EXPLOSIVES	☐	☐	☐	☐
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	☑	☐	☐	☐
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	☑	☐	☐	☐
8. NONCOAL WASTE	☐	☐	☐	☐
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	☐	☐	☐	☐
10. SLIDES AND OTHER DAMAGE	☐	☐	☐	☐
11. CONTEMPORANEOUS RECLAMATION	☐	☐	☐	☐
12. BACKFILLING AND GRADING	☐	☐	☐	☐
13. REVEGETATION	☐	☐	☐	☐
14. SUBSIDENCE CONTROL	☐	☑	☐	☐
15. CESSATION OF OPERATIONS	☐	☐	☐	☐
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	☑	☐	☑	☐
b. DRAINAGE CONTROLS	☑	☐	☑	☐
17. OTHER TRANSPORTATION FACILITIES	☐	☐	☐	☐
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	☐	☐	☐	☐
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	☐	☐	☐	☐
20. AIR QUALITY PERMIT	☐	☐	☐	☐
21. BONDING & INSURANCE	☐	☐	☐	☐

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 007/035

Inspection Date 10/12/95

Please number comments to correspond with topics on previous page.

As a result of a partial inspection, the following environmental measures were worthy of written comments:

Diversions. Haul road diversions were recently graded and no problems were observed.

Drainage and a diversion adjacent to the spoil pile needs some attention. These were covered in a note to Mr. Comas, together with a sketch.

Sediment Ponds & Impoundments. All ponds and impoundments were dry except for pasture pond, coal runoff pond, and refuse toe pond. None were discharging.

Revegetation. Observed the seeded/revegetated outslope of the refuse pile. While there are some differences in density, species composition, vigor, and other plant indices, concluded the following:

(1) No significant erosion was observed in the revegetated/seeded areas and

(2) The seeded species produced an abundant seed crop which should result in added plant establishment should weather conditions remain favorable.

Copy of report mailed to

Copy of report given to

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT007/035

Inspection Date 10/12/95

Please number comments to correspond with topics on previous page.

The seeded acid/toxic road project does not have the perennial plant density that was observed at the refuse outslope. This project was seeded one year later, and perhaps premature to fully evaluate effectiveness.

Roads: Haul roads had been watered and recently regraded. With the regrading the haul roads for the most part are crowned. Also, in some areas small berms had remained after the initial grading. This was mentioned in the last inspection. All such berms have been eliminated with the regrading.

Some ancillary roads are in need of routine maintenance.

Copy of report mailed to Co. Gen/D. Mattingley; OSM/D. Griffin; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tim J. Malencik No. 26

10/13/95

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE