State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Inspection Report

Permit Number:	**C0070035**
Inspection Type:	PARTIAL
Inspection Date:	Thursday, February 13, 2014
Start Date/Time:	2/13/2014 8:30:00 AM
End Date/Time:	2/13/2014 11:00:00 AM
Last Inspection:	Thursday, January 16, 2014

Inspector: Karl Houskeeper,

Weather: Clear Skies. Temp. 45 Deg. F

InspectionID Report Number: 3750

Accepted by: jhelfric
2/20/2014

Representatives Present During the Inspection:	
Company	Rusty Netz
OGM	Karl Houskeeper

Permitee: **SUNNYSIDE COGENERATION ASSOCIATES**
Operator: **SUNNYSIDE COGENERATION ASSOCIATES**
Site: **SUNNYSIDE REFUSE & SLURRY**
Address: **PO BOX 159, SUNNYSIDE UT 84539**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

241.25	**Total Permitted**
196.65	**Total Disturbed**
5.35	**Phase I**
5.35	**Phase II**
5.35	**Phase III**

Mineral Ownership

- ☐ Federal
- ☐ State
- ☐ County
- ☑ Fee
- ☐ Other

Types of Operations

- ☐ Underground
- ☐ Surface
- ☐ Loadout
- ☐ Processing
- ☑ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Karl R. Houskeeper

Inspector's Signature:

Karl Houskeeper,
Inspector ID Number: 49

Date Thursday, February 13, 2014

Note: This inspection report does not constitute an official finding of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

UTAH DNR OIL, GAS & MINING

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☐	☐	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☐	☐	☐	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5. Explosives	☑	☑	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☑	☐	☑	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☐	☑	☐
8. Noncoal Waste	☑	☐	☐	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

The mine identification was observed at the entrance into the mining permit area. The sign is posted on a power pole and contains the required information as required by the Utah R645 Coal Rules.

4.a Hydrologic Balance: Diversions

The diversios within the permit area are open and fubctional.

6. Disposal of Excess Spoil, Fills, Benches

Excess spoil pile #2 phase #2 is actively receiving spoil material. Work has been done on a portion of the out slope of excess spoil pile #1 to extinguish the smokers.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. No visible hazards were observed.