0014

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Partial: XX Complete: ___ Exploration XX
Inspection Date/Time: January 11, 1994/01:00am-02:30pm
Date of Last Inspection: November 9, 1993

Mine Name: Blackhawk Site County: Carbon Permit Number: ACT/007/038
Permittee and/or Operator's Name: Cyprus Plateau Mining/Western Coal Company
Business Address: P. O. Box PMC, Price, UT 84501
Type of Mining Activity: Underground____ Surface____ Prep. Plant____ Other XX
Officials(s): State: Stephen J. Demczak Company: _____
Federal Official(s): _____ Weather Conditions: Cool 20's
Existing Acreage: Permitted-11,500 Disturbed-3.7 Regraded-_ Seeded-0 Bonded-3.7
Increased/Decreased: Permitted-____ Disturbed-__ Regraded-__ Seeded-__ Bonded-____
Status: X Exploration/___ Active/___ Inactive/__ Temp Cessation/__ Bond Forfeiture
Reclamation (__ Phase I/__ Phase II/__ Final Bond Release/__ Liability_____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[XX]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____ date	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT
(Continuation sheet)

PERMIT NUMBER: ACT/007/038 DATE OF INSPECTION: January 11, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The exploration permit has been extended for two years. There has been no exploration work being performed. The fan is shut down and the portals are sealed. Cyprus Mining is in the process of compiling a Mining and Reclamtion permit for this property. The exploration site will be used in conjunction with the proposed mine site. Therefore, reclamation of the exploration site would be non-productive.

4a. Diversions -

The diversions showed no signs of breaching or erosion and appeared to be performing as designed. No water flow in diversion for several months due to weather conditions.

4c. Other Sediment Control Measures -

The silt fences were maintained and functioning as designed. There were no signs of by passing of the silt fences. The catch basins were not impounding water and had no signs of erosion.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Cyprus Plateau Mining/Western Coal Company
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: January 19, 1994

Inspector's Signature and Number: Stephen J. Demczak #39