Incoming C0070041

OK

0077

From: "Michael Hansen" <Mhansen@rbgengineering.com>
To: <James_Kohler@blm.gov>, <Jeff_McKenzie@blm.gov>, <Stan_Perkes@blm.gov>, <Steve_Falk@blm.gov>, <steve_rigby@blm.gov>, <jllewelyn@co.carbon.ut.us>, <ecc@emerytelcom.net>, <sunny1@emerytelcom.net>, "Brad Price" <bprice@rbgengineering.com>, "Rob johnson" <robj@rbgengineering.com>, <bretdixon@utah.gov>, <davemarble@utah.gov>, <karlhouskeeper@utah.gov>, <marcstilson@utah.gov>, <pamgrubaughlittig@utah.gov>, <petehess@utah.gov>, <waynehedberg@utah.gov>, <dshaver@utahamerican.com>
Date: 8/21/2006 7:24:49 PM
Subject: Grassy Trail Dam Monitoring Information 08-19-06 Seepage Readings and Site Photos

Attached are the Seepage readings and Site Photos for 08-19-06

- Grassy Trail Dam seepage readings
- Observation photos from August 19, 2006

Michael Hansen
Engineering Geologist

RB&G ENGINEERING Inc.
1435 West 820 North
Provo Ut. 84601

Ph 801-374-5771
SLC 801-521-5771
Fax 801-374-5773

email mhansen@rbgengineering.com

GRASSY TRAIL DAM SEEPAGE READINGS

Dam Crest Elev(ft)		7600.0		Seep1:Toe Drain		Seep 2: Left Abutment (East Seep)		Seep 3: Right Abutment (West Seep)			
Spillway Elev. (ft)		7592.5									
		Seep Location:									
Date	Initials	Reservoir Elev.	Reservoir Characteristics	GAL/MIN	Water Characteristics	GAL/MIN	Water Characteristics	GAL/MIN	Water Characteristics	Weather Conditions	Temperature (F)
8/19/06	MNH	7590.4		Dry		16.7	Clear	0.45	Clear	Sunny	82

Looking West
08/19/2006

Looking West
08/19/2006

Looking West
08/19/2006


Looking East
08/19/2006

Looking East
08/19/2006

Looking East
08/19/2006

West Abutment
08/19/2006

East Face
08/19/2006

East Abutment
08/19/2006