0082

Incoming C0070041

From: "Michael Hansen" <Mhansen@rbgengineering.com>
To: <James_Kohler@blm.gov>, <Jeff_McKenzie@blm.gov>, <Stan_Perkes@blm.gov>, <Steve_Falk@blm.gov>, <steve_rigby@blm.gov>, <jllewelyn@co.carbon.ut.us>, <ecc@emerytelcom.net>, <sunny1@emerytelcom.net>, "Brad Price" <bprice@rbgengineering.com>, "Rob johnson" <robj@rbgengineering.com>, <bretdixon@utah.gov>, <davemarble@utah.gov>, <karlhouskeeper@utah.gov>, <marcstilson@utah.gov>, <pamgrubaughlittig@utah.gov>, <petehess@utah.gov>, <waynehedberg@utah.gov>, <dshaver@utahamerican.com>
Date: 9/11/2006 8:18:32 AM
Subject: Grassy Trail Dam Monitoring Information 9-8-06 Seepage Readings and Site Photos

Attached are the Seepage readings and Site Photos for 09-8-06

- Grassy Trail Dam seepage readings
- Observation photos from September 8, 2006

Michael N. Hansen, P.G.
Engineering Geologist

RB&G ENGINEERING Inc.
1435 West 820 North
Provo Ut. 84601

Ph 801-374-5771
SLC 801-521-5771
Fax 801-374-5773

email mhansen@rbgengineering.com

GRASSY TRAIL DAM SEEPAGE READINGS

Dam Crest Elev(ft)		7600.0									
Spillway Elev. (ft)		7592.5									
		Seep Location:	Seep1:Toe Drain			Seep 2: Left Abutment (East Seep)		Seep 3: Right Abutment (West Seep)			
Date	Initials	Reservoir Elev.	Reservoir Characteristics	GAL/MIN	Water Characteristics	GAL/MIN	Water Characteristics	GAL/MIN	Water Characteristics	Weather Conditions	Temperature (F)
8/19/06	MNH	7590.4		dry		16.7	Clear	0.45	Clear	Sunny	82
8/25/06	MNH	7590.2		1.1	muddy storm run off	15.8	Clear	0.77	Clear	heavy rain/hail	52
9/1/06	MNH	7590.1		dry		15.0	Clear	0.44	Clear	Sunny	83
9/8/06	MNH	7589.6		dry		15.0	Clear	0.44	Clear	rain	65


Looking West
09/08/2006

Looking West
09/08/2006

Looking West
09/08/2006

Looking East
09/08/2006

Looking East
09/08/2006

Looking East
09/08/2006

West Abutment
09/08/2006

Down stream face
09/08/2006

East Abutment
09/08/2006