0005 10-13-87

File gd on

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002

Inspection Date September 16, 1987

Permittee/Operator Name Western States Minerals Corp.

Business Address 4975 Van Gordon Street

City Wheat Ridge State Colo. Zip 80033

Mine J.B. King ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) None

State Official(s) Harold G. Sandbeck and Bill Malencik

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 6:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection August 14, 1987 Weather conditions Clear/Warm

Acreage 480 ☒ Permitted 30 ☒ Disturbed 30 ☒ Regraded 30 ☒ Seeded 30 ☒ Bonded

Enforcement Action Four (4) TON's

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
a – Stream channel diversions	☒	☐	☐	☒
b – Diversions	☒	☐	☐	☐
c – Sediment ponds and impoundments	☒	☐	☐	☐
d – Other sediment control measures	☒	☐	☐	☒
e – Surface and groundwater monitoring	☒	☐	☐	☐
f – Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
a – Construction	☒	☐	☐	☐
b – Drainage controls	☒	☐	☐	☐
c – Surfacing	☒	☐	☐	☐
d – Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date September 16, 1987

Please number comments to correspond with topics on previous page.

General Comments: On this complete inspection, DOGM was accompanied by Joe Funk (OSM oversight inspector). Ground conditions were dry.

1.) Permits: Phase I release was approved 03/12/86. $126,078 remains as a surety bond with Seaboard Surety. The certificate of insurance is not required for this site. As of 01/15/86, all stipulations have been met.

2.) Signs and Markers: Entrance sign at gate was repainted. All information is correct and current. Perimeter markers were seen during the inspection.

4.a.) Stream Channel Diversions: TDN No. 87-02-006-009, 2 of 4 was received by the undersigned inspector. The channel was repaired by the operator before the October 1, 1987 TDN deadline. On September 30, 1987, the undersigned inspector field checked and abated the repair work.

4.c.) Other Sediment Control Measures: TDN No. 87-02-006-009, 3 of 4 was received by the undersigned inspector. The 20+ 9+ inch rills and gullies were repaired by the operator before the October 1, 1987 TDN deadline. On September 30, 1987, the repair work was abated. The operator intends to spread seed on the repaired disturbed areas and also on the pond embankments as soon as the seed arrives.

Copy of report mailed to Tom Hughes, W.S. and Brian Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harvey D. Sandbeck September 29, 1987 No. 27

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE