RE 6-16-87

file

LPB

UTAH NATURAL RESOURCES
Oil, Gas & Mining

0008

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002

Inspection Date 6/11/87

Permittee/Operator Name Western States Minerals Corp.

Business Address 4975 Van Gordon Street

City Wheat Ridge State Colo Zip 8003

Mine J. B. King ☐ Surface ☒ Underground ☐ Other

County Emery State Ut.

Company Official(s) None

State Official(s) Wm. J Malencik, Holland Shepherd

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 10:00 ☒ a.m. ☐ p.m. ☐ Partial ☒ Complete

Date of last inspection May 18, 1987 Weather conditions Clear/Warm.

Acreage 480 ☑ Permitted 28± ☑ Disturbed 28± ☑ Regraded 28± ☑ Seeded 28± ☑ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
a. Stream channel diversions	☒	☐	☐	☐
b. Diversions	☒	☐	☐	☐
c. Sediment ponds and impoundments	☒	☐	☐	☒
d. Other sediment control measures	☒	☐	☐	☐
e. Surface and groundwater monitoring	☐	☐	☒	☐
f. Effluent limitations	☐	☐	☒	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

LPB

UTAH NATURAL RESOURCES
Oil, Gas & Mining

Page ___ of ___

INSPECTION REPORT COMMENTS

Permit No. _____

Inspection Date _____

Please number comments to correspond with topics on previous page.

Introduction. No mine officials accompanied the undersigned to the mine site. This inspection did not include a record review of the mine company records. Within the past month additional work was performed at the mine site. The work was of a maintenance nature involving gulley & rill erosion abatement.

[4c] Sediment pond was stable and did not contain water.

[13] Revegetation. Grasses were green & seed heads were visible on the wheatgrasses, needle & thread, rice grass, and cheatgrass, an invader. The shrubs have all made good growth, especially the fourwing saltbush and shadscale. Greasewood, a non planted species, was observed from time to time, being most noticeable near the edge (undistributed) and lower mine site areas.

Gate has been repaired and was closed during the inspection

Livestock. No livestock were observed in the reclaimed area, nor were any observed in range areas contiguous to the mine site.

Copy of report mailed to Mike O'Donnel, W.S.; Donna Griffin, OSM

Copy of report given to Joe Helfrich

Inspector's signature Jim F. Smalenick 6/12/87 No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE