✓ 4-2-87 RY 0009

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002
Inspection Date 5/28/87

Permittee/Operator Name Western States Mineral Corp.
Business Address 4975 Van Gordon Street
City Wheatridge State Colo Zip 80033
Mine J.B. King ☐ Surface ☑ Underground ☐ Other
County Emery State Utah
Company Official(s) None
State Official(s) Tom Munson
Time of inspection 12:00 ☐ a.m. ☑ p.m. to 4:00 ☐ a.m. ☑ p.m. ☑ Partial ☐ Complete
Date of last inspection 4/21/87 Weather conditions Sunny
Acreage 450 ☑ Permitted 28.2 ☑ Disturbed 28.2 ☑ Regraded 28.2 ☑ Seeded 28.2 ☑ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☒
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 5/18/87

Please number comments to correspond with topics on previous page.

4a Stream Channel Diversions - Work has begun on the Stream Channel Diversions namely the main channel and the feeder ditch in the areas of excessive erosion. Duane Tiller of Western States Minerals was overseeing the operation. The channel had been reshaped and prepared for the placement of a filter blanket and riprap. The preliminary shaping of the channels looked satisfactory. The remainder of the work was to be carried out by the end of this week.

4b Other Sediment Control Measures - The repair work on the rill and gullies was completed and done in a satisfactory manner to minimize disturbance to surrounding vegetation

13. Revegetation - Reseeding of the disturbed areas associated with the repair work

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 5/18/87

Please number comments to correspond with topics on previous page.

end of any bare spots is to be carried out by the end of the week.

Copy of report mailed to John Kathmann, Charles Williams

Copy of report given to Joe Helfrich

Inspector's signature Thomas Munson 6/12/87 No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer