0015

File

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002
Inspection Date January 6, 1988

Permittee/Operator Name Western States Minerals Corp.
Business Address 4975 Van Gordon Street
City Wheat Ridge State Co. Zip 80033
Mine J. B. King ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) None
State Official(s) Harold G. Sandbeck and Daron Haddock
Time of inspection 12:00 ☐ a.m. ☒ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection December 8, 1987 Weather conditions Clear/Cold
Acreage 480 ☒ Permitted 30 ☒ Disturbed 30 ☒ Regraded 30 ☒ Seeded 30 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a – Stream channel diversions	☒	☐	☐	☐
b – Diversions	☒	☐	☐	☐
c – Sediment ponds and impoundments	☒	☐	☐	☐
d – Other sediment control measures	☐	☐	☐	☐
e – Surface and groundwater monitoring	☐	☐	☐	☐
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date January 6, 1988

Please number comments to correspond with topics on previous page.

This mine site had received a severe, high intensity, short duration thunderstorm causing damage as noted in inspection reports dated November 13, 1987 and December 8, 1987. Major redesign work is required since this site has received 2 previous damaging storm events. A meeting between WSMC and DOGM is scheduled for January 27, 1988 to discuss conceptual design repair work. The site was covered with about 6" of snow.

Copy of report mailed to Tom Hughes, WSN; Brian Smith, OSM

Copy of report given to Joe Helfrich, DOGM

Inspector's signature Harold D. Sam 11 Jan. 88 No. 27

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer