7/00

0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002

Inspection Date 12/6/89

Permittee/Operator Name WESTERN STATES MINERALS

Business Address 4975 VAN GORDON STREET

City WHEAT RIDGE State COLO Zip 80033

Mine J. B. KING ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

Company Official(s) NONE

State Official(s) TOM MUNSON

Time of inspection 9 : 36 ☒ a.m. ☐ p.m. to 10 : 30 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/8/89 Weather conditions

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 12/6/89

Please number comments to correspond with topics on previous page.

2) The sign by the main gate was repainted and was easily legible.

4)(b) diversions - The upper right fork of main channel was inspected and appeared to be holding up well with some displacement of the riprap between check dams. The check dams were holding up well and appeared to provide the necessary protection for the channel.

d) The silt fences have been upgraded and cleaned and all appeared to be in good working order

13) The revegetation of problem areas in need of reseeding, etc. was carried out and looked acceptable to improve reclamation success. The straw mulch was in some areas bunching due to lack of adequate crimping. Overall it looked much better than past attempts at repairs.

Copy of report mailed to WSM: AL GORDON
OSM / BRIAN SMITH, DOGM / JOE HELFRICH

Copy of report given to PFO

Inspector's signature Thomas Munson No. 25

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

11-13-89 9:00

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002

Inspection Date November 8, 1989

Permittee/Operator Name Western States Minerals

Business Address 4975 Van Gordon Street

City Wheat Ridge State Colo Zip 80033

Mine L.B King ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 3:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 9/19/89 Weather conditions Clear/Windy/Cool

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 11/8/89

Please number comments to correspond with topics on previous page.

General Comments. The operator has performed additional work suggested by the Division. This work is briefly highlighted below.

Signs & Markers. The ID sign by the main gate is starting to fade. It is suggested that the sign be repainted ie, the lettering before it becomes illegible. The upper I.D sign is in excellent shape

Sediment Pond. The sediment pond was dry, stable, and showed no sign of discharge.

Revegetation. Areas contiguous to some of the silt fences involved in previous maintenance work were harrowed, broadcast seeded, mulched, & reharrowed. This included the road and a small adjacent area. The road that was seeded involved two segements ie, the access road that was cutoff as a result of realigned protection fence, and the road that went up to the main undisturbed channel. No livestock nor tracks observed on site.

Road. Operator recently regraded the access road outside of the protection fence

Copy of report mailed to {WSM: Al Gordon
{SLC For: OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tim J. Malencik No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

11/9/89

DOGM/IR-2 an equal opportunity employer 11/86 001049