4-14-89
7100

0013

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gdh RVS

inspection report

Permit No. INA/015/002
Inspection Date April 6, 1989

Permittee/Operator Name Western States Minerals
Business Address 4975 Van Gordon St.
City Wheat Ridge State CO Zip 80033
Mine J.B. King ☐ Surface ☒ Underground ☐ Other
County Emery State UT
Company Official(s) None
State Official(s) Bill Wakmack
Time of inspection 10:00 ☒ a.m. ☐ p.m. to 11:30 ☒ a.m. ☐ p.m. ☐ Partial ☒ Complete
Date of last inspection March 7, 1989 Weather conditions Clear & warm
Acreage 480 ☒ Permitted 30 ☒ Disturbed 30 ☒ Regraded 30 ☒ Seeded 30 ☒ Bonded
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☐
e Surface and groundwater monitoring	☒	☐	☐	☐
f Effluent limitations	☒	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☐	☐	☒	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
a Construction	☐	☐	☒	☐
b Drainage controls	☒	☐	☐	☐
c Surfacing	☐	☐	☒	☐
d Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☒	☒

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. UT/015/002

Inspection Date 4/6/89

Please number comments to correspond with topics on previous page.

GENERAL: FOR THE MOST PART, THE MINE SITE WAS DRY. HOWEVER, MOIST CONDITIONS STILL EXIST ALONG THE MAIN DIVERSION CHANNEL & IN AREAS WHERE PLANT GROWTH IS DENSE. POND WAS DRY.

2. SIGNS & MARKERS: THE PERMIT NUMBER ON THE MINE I.D. SIGN IS STARTING TO FADE ALTHOUGH STILL LEGIBLE AT THIS TIME.

13. REVEGETATION: NEW GRASS SPOUTS WERE EVIDENT THROUGHOUT THE SITE, SHRUBS WERE STARTING TO "LEAF" OUT.

14. SUBSIDENCE: SUBSIDENCE AREA SHOWED NO SIGNS OF INCREASED SETTLING OR INSTABILITY.

18. SUPPORT FACILITIES: THE PERIMETER FENCE IS STILL IN GOOD REPAIR, FENCE "SAGGING" HAS NOT YET DEVELOPED. CATTLE WERE NOT OBSERVED ON THE ADJOINING AREAS.

Copy of report mailed to AL GORDON (WSM), JOE HELFRICH (DOSM), BRIAN SMITH (OSM)

Copy of report given to PFO

Inspector's signature William A. Warmack 4/7/89 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer