5-25-89 0014

7100

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gh RCS

inspection report

Permit No. IUA/015/002

Inspection Date MAY 11, 1989

Permittee/Operator Name WESTERN STATES MINERALS

Business Address 4925 VAN GORDON ST.

City WHEAT RIDGE State CO Zip 80033

Mine JB KING ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) NONE

State Official(s) BILL WAKEMACK, HENRY SAUER, BRENT STETTLER, TOM MUDSON

Time of inspection 12:00 ☐ a.m. ☒ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection APRIL 6, 1989 Weather conditions OVERCAST + WINDY

Acreage 480 ☒ Permitted 30 ☒ Disturbed 30 ☒ Regraded 30 ☒ Seeded 30 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d – Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f – Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 5/11/89

Please number comments to correspond with topics on previous page.

GENERAL: DIVISION PERSONNEL (A. SAUER, B. STETTLER, T. MUNSON & B. WARMACK) INSPECTED THE SITE. THE POND AT THE NORTHWESTERN CORNER OF THE PROPERTY WAS DRY WHICH MAY INDICATE PRECIPITATION LEVELS ARE WELL BELOW NORMAL.

4d. OTHER SEDIMENT CONTROLS: DUE TO THE EXTREME WINDS THE AREA HAS EXPERIENCED RECENTLY, A SILT FENCE ON THE OUTSLOPE OF THE RECLAIMED REFUSE PILE WAS LOOSE. UPON REINSTALLATION, THE OPERATOR IS REMINDED TO KEY THE STRUCTURES IN.

18. SUPPORT FACILITIES: THE PERIMETER FENCE IS STILL INTACT; FENCE WIRE & POSTS APPEAR TO BE HOLDING UP TO THE CATTLE PRESSURE.

Copy of report mailed to AL GORDON (WSM), JOE HELFRICH (DOGM), BRIAN SMITH (OSM)

Copy of report given to PFO

Inspector's signature William A. Warmack 5/12/89 No. 30

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer