3-1-89
7100

0016

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002

Inspection Date 2/1/1989

Permittee/Operator Name WESTERN STATES MINERALS CORPORATION

Business Address 4975 VAN GORDON ST. WHEAT RIDGE, CO. 80033

City WHEAT RIDGE State CO. Zip 80033

Mine J. B. KING ☐ Surface ☒ Underground ☐ Other

County EMERY State UTAH

~~Company~~ STATE Official(s) HENRY SAUER AND BILL WARMACK

~~State~~ COMPANY Official(s) NONE

Time of inspection 11:30 ☒ a.m. ☐ p.m. to 12:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 1/4/89 Weather conditions CLEAR AND MILD

Acreage ☐ Permitted 480 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded 30

Enforcement Action ~~NONE~~ - FOLLOW-UP ACTION ON N-89-32-1-1 AND SUBSEQUENT TERMINATION

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☒	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	X	☐	☒	☐
5. Explosives	X	☐	☒	☐
6. Development waste and spoil disposal	X	☐	☒	☐
7. Coal processing waste	X	☐	☒	☐
8. Noncoal waste	X	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	X	☐	☒	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	X	☐	☒	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☐	☐	☒	☐
— Maintenance	X	☐	☒	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 2/1/1989

Please number comments to correspond with topics on previous page.

GENERAL:

This complete inspection served as a follow-up on the abatement of NOV #89-32-1-1 which was scheduled for completion on February 2, 1989. After review of the mine site, the NOV was terminated from the Price office. Correspondence records were review at the Salt Lake City office and found in good order.

4B Diversions:

The berms of the contour ditches along the fill slope have been trampled by cattle and need to be repaired this spring.

4D Other Sediment Control Measures:

Many of the silt fences located on the fill slope need repair (ie additions of fence and berms to prevent drainage ~~from~~ around the existing fences) as soon as weather permits.

18. Support Facilities: The perimeter fence has been repaired. Repairs consist of: addition of one barbed wire strand; installment of fence stays, tightening of all barbed wire strands. The tightness of the barbed wire must be monitored this spring and summer to determine if cedar stretch posts are necessary to maintain strand tightness.

Copy of report mailed to LARRY JOHNSON, WESTERN STATES MINERALS

Copy of report given to BRIAN SMITH, OSM; JOE HELFRICH, DOGM

Inspector's signature Henry Sauer #32 No. #32

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE