0008

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Get page

inspection report

Permit No. ACT/015/002

Inspection Date 9/28/90

Permittee/Operator Name Western States Minerals

Business Address 4975 Van Gordon Street

City Wheat Ridge State Colo Zip 80033

Mine J.B. King ☐ Surface ☒ Underground ☐ Other

County Emery State Ut.

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 5: ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 8/17/90 Weather conditions

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☒
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 9/28/90

Please number comments to correspond with topics on previous page.

General Comments. The operator recently repaired rill erosion on the mine site. Straw and rocks were placed in the rills to stablize the rilling.

The general area had been hit by several storms. The state was repairing roads on the blacktop highway between Hidden Valley & L.B King. Several drainage channels topped the highway.

Stream Channel Diversion. The S.E. undisturbed channel needs a little more rip rapp. protection to augment the work done last spring

Sediment Pond. Sediment pond was dry stable and contain no runoff. Some weeds were observed in the pond bottom none to speak of on the embankments.

Other Sediment Control. Operator has continued the practice of stablizing rills through the use of straw and rocks. He advised me over the phone after the inspection that he is develing a plan to evaluate the coal refuse area and what measures or combination of measures would be most effective in the long run.

Copy of report mailed to WSM/Frank Filas; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

10/9/90