7100 0017 M/015/002

UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002
Inspection Date Jan 5, 1990

Permittee/Operator Name Western States Minerals
Business Address 4995 Van Gordon St.
City Wheat Ridge State Colo. Zip 80033
Mine J.B. King ☐ Surface ☒ Underground ☐ Other
County Emery State
Company Official(s) None
State Official(s) Bill Malencik
Time of inspection 10:30 ☒ a.m. ☐ p.m. to 3:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete
Date of last inspection 12-6-89 Weather conditions
Acreage ☐ Permitted ☐ Disturbed ☐ Regraded ☐ Seeded ☐ Bonded
Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☒	☐	☐	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☒	☐	☐	☒
— Drainage controls	☒	☐	☐	☒
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☒
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 1/5/90

Please number comments to correspond with topics on previous page.

General Comments: The mine site was dry and no evidence of any fall runoff.

PERMIT. The current permit expires August 12, 1990. The operator should contact Pam Kittig, SLC and discuss its plans and time frames on a permit renewal.

Sediment Pond. Sediment pond inspection was completed by Jim Blackburn on Oct 10, 1989. A copy of the report was sent to the Price Field Office. The report indicated the pond was stable.

The pond was checked on 1/5/90 and no problems were observed. The pond was dry and no cattle nor cattle tracks were observed adjacent to the pond.

Revegetation. Some seedling emergence was observed in the reseeded areas completed 10/12/89. This for the most part was spotty and largely attributable to the lack of soil moisture.

Subsidence. Areas of outstanding subsidence cracks on the upper bench area were observed and very little evidence of the former cracks could be seen.

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date Jan 5, 1990

Please number comments to correspond with topics on previous page.

Road The road that passed through the fenced/enclosed mine site was changed last fall. The road was realigned and now is located outside of the fenced mine site. This was necessary because the gate was most often open and cattle during spring/fall/winter grazed on the mine revegetated areas. The road alignment was approved by the Division. Drainage controls on the road appear to be adequate. The road appears to have been regraded on the lower steeper portion.

Copy of report mailed to {WSM/Al Gordon
SLC For: Brain Smith/OSM, Joe Helfrich/DOGM

Copy of report ~~given to~~ filed PFO

Inspector's signature Tim J Thalenick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

1/5/90

DOGM/IR-2

an equal opportunity employer

11/86 001049