UT7100

0020

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Gd page

inspection report

Permit No. ACT/015/002

Inspection Date 5/7/91

Permittee/Operator Name Western States Minerals Corp.

Business Address 4975 Van Gordon St.

City Wheat Ridge State Colo Zip 80033

Mine J.B. King ☐ Surface ☒ Underground ☐ Other

County Emery State Ut.

Company Official(s) None

State Official(s) Bill Malencik, Hugh Klein

Time of inspection 8:30 ☒ a.m. ☐ p.m. to 12:00 noon ☐ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 4/15/91 Weather conditions Clear / Windy

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action None

✓ Maintenance - Siltfences

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 5/7/91

Please number comments to correspond with topics on previous page.

General Comments. Site conditions were about the same as covered in the previous report. The mine site and adjacent areas were very dry and showed no evidence of recent rains.

Sediment Pond. The pond was dry. Some weeds had started growth in the bottom of the pond. This would indicate a small amount of water had accumulated in the pond in the early spring. The pond was stable, has one non-erodible spillway and showed no evidence of discharge.

Siltfences. Siltfences were checked and several had deteriorated. Some because of fabric breakdown, others because the fabric had become detached from the net wire. Straw had recently been placed in most of the erosion rills above and below the silt fences.

Revegetation. Saltbush plants are doing well. This is especially true adjacent to the main drainage channel.

Checked the reference area. Markers are in place.

Subsidence. Checked subsidence area and no problems were noted.

Copy of report mailed to Western States/Dwight Crossland; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature [signature] No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

5/10/91

DOGM/IR-2

an equal opportunity employer

11/86 001049