0026

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

gdt pgl

INSPECTION REPORT

INSPECTION DATE & TIME: 2/13/91
8:30am-12:00pm

Permittee and/or Operators Name: Western States Minerals Corp.
Business Address: 4975 Van Gordon Street
Mine Name: J.B. King Permit Number: ACT 015/002
Type of Mining Activity: Underground x Surface___ Other___
County: Emery
Company Official (s): _____
State Official(s): Susan M. White
Partial: x Complete: Date of Last Inspection: 1/10/91
Weather Conditions: Fair, cool, and very windy
Acreage: Permitted 480 Disturbed 30 Regraded 30 Seeded 30 Bonded30

Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	(x)	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(x)	( )	( )	( )
b. DIVERSIONS	(x)	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	( )	( )	(x)
d. OTHER SEDIMENT CONTROL MEASURES	(x)	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	(x)	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	(x)	( )
7. COAL PROCESSING WASTE	( )	( )	(x)	( )
8. NONCOAL WASTE	( )	( )	(x)	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(x)	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	(x)	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	(x)	( )	( )	( )
14. SUBSIDENCE CONTROL	(x)	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	(x)	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	(x)	( )
b. DRAINAGE CONTROLS	( )	( )	(x)	( )
c. SURFACING	( )	( )	(x)	( )
d. MAINTENANCE	( )	( )	(x)	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	(x)	( )
18. SUPPORT FACILITIES				

an equal opportunity employer

INSPECTION REPORT

(continuation sheet) Page 2 of 2

PERMIT NUMBER: ACT/015/002 DATE OF INSPECTION: 2/13/91

(Comments are Numbered to Correspond with Topics Listed Above)

The site was essentially dry on the day of inspection. Snow remained only in isolated protected pockets. Cattle were observed in areas surrounding in the mine site, however they were much less concentrated than the last inspection. The site appeared unchanged from the last site visit.

A meeting was held on January 21, 1991 with Mr. Frank Filas to discuss on site repair work. The drainage area which was reworked in 1989 will be set aside and the bond clock restarted. Mr. Filas is investigating husbandry practices in the area to determine if selective practices are allowed.

1. Signs and markers were in place.

4c. The sediment pond was dry. Large dried Kochia weeds remain in the bottom of the pond. The operator was requested to send sediment pond inspection reports to the Salt Lake City office. The operator had been sending the inspections to the Price field office.

14. An attempt was made to locate some of the archeological sites reported in the permit. Two sites were found. Subsidence has had no effect on these sites.

Copy of this Report:
Mailed to: Frank Filas/ Western States; John Kathman/ OSM
Given to: Joe Helfrich

Inspectors Signature & Number: Susan White #35 Date: 2/14/91