UTAH NATURAL RESOURCES
Oil, Gas & Mining
3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

0007

inspection report

Permit No. Act/015/002
Inspection Date Sept 30, 1992

Permittee/Operator Name Western States Minerals
Business Address Suite 130, 250 S. Rock Blvd.
City Reno State NV Zip 89502
Mine J.B. King Act/015/002 ☐ Surface ☒ Underground ☐ Other
County Emery State Ut
Company Official(s) None
State Official(s) Bill Malencik
Time of inspection 10:00 ☒ a.m. ☐ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete
Date of last inspection 8/20/92 Weather conditions Clear/Windy
Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded
Enforcement Action None - Prior NOV still outstanding:
N91-35-06-01 (stream channel diversion)
N91-35-07-01 (Erosion)
N91-32-06-01 (failure to comply with permit & regs) Feeder Diversion

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☒	☐	☒
— Diversions	☐	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☒	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☒	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 9/30/92

Please number comments to correspond with topics on previous page.

General Comments.

- Outstanding violations are still pending. The three violations are identified on page 1 herein. Two were issued in November 1991 and the other in December 1991; abatement dates on the three violations have been extended to 12/30/92.

The three violations have gone through part of the administrative hearing with findings, conclusion and order issued by the Director on March 10th, 1992.

Sediment Pond. Sediment pond was observed. The small ditch adjacent to the sediment pond where it interfaces with the sediment pond shows some initial signs of erosion. It is suggested when the permittee does on site work to abate erosion violations that protection be provided on this item at the same time.

Other Sediment Control. No additional erosion control has been implemented by the permittee on the coal refuse outslope since silt fences/straw in the rills has been in place. The work has consisted of maintenace that has not minimized erosion to the extent possible that resulted in the prior violation.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 9/30/92

Please number comments to correspond with topics on previous page.

Non Coal Waste. The mine site is in good condition with respect to mine trash, cans, bottles etc.
Support Facilities. Fences and gates were observed in several areas, primarily northerly and northwesterly segements of the mine site. The fences were in a good state of repair. No recent signs of cattle were noted in the fenced area.

Copy of report mailed to WSM/D.V. Crossland; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

10/2/92