0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd page

inspection report

Permit No. ACT/015/002

Inspection Date June 26, 1992

Permittee/Operator Name Western States Minerals

Business Address 84 Glen Carran Circle

City Sparks State NV Zip 89431

Mine J.B King (Reclaimed) ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection May 6, 1992 Weather conditions Cloudy / Few Raindrops

Acreage 480 ☐ Permitted ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/002

Inspection Date JUNE 26, 1992

Please number comments to correspond with topics on previous page.

General Comments. The mine site was dry. However, the plant growth on the established perennials both on the mine site and on the adjacent range lands was above normal

Signs & Markers. Required signs and markers were in place. This is based on a spot checks on several areas as related to the perimeter markers.

Sediment Pond. The sediment pond was dry, stable and the spillway showed no evidence of recent runoff. The inlet showed signs of sedimentation dropout. This took place on the high intensity storms in 1991.

Sediment Control Measures. The silt fences on the refuse pile are still in place. The permittee is considering some other environmental control measures that may be more effective and require less maintenance.

Revegetation. Indian rice grass plants varied in height between 12-16" in height. The four wing salt bush plants had excellent leader growth (8"-12").

Copy of report mailed to WSM/Dwight Crossland; OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed PFO

Inspector's signature Jim J. Smalenick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

7/6/92

DOGM/IR-2 an equal opportunity employer 11/86 001049