0014

act pgl

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/002

Inspection Date March 27, 1992

Permittee/Operator Name Western States Minerals Corporation

Business Address 84 Glow Canyon Circle

City Sparks State NV Zip 89431

Mine U.B. King ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None - Concurred by phone with Mr. Blackburn prior to the inspection

State Official(s) Bill Malencik

Time of inspection 9:30 ☒ a.m. ☐ p.m. to 2:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection February 5, 1992 Weather conditions Cloudy/Temp lower 60°

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action None

Prior violations N 91-35-6-1, N 91-35-7-1 & N 91-32-6-1 are still pending.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☒	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☒	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☒	☐	☐	☒
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/002

Inspection Date 3/27/92

Please number comments to correspond with topics on previous page.

Outstanding Violations. The three violations mentioned on page 1 herein are still pending the administrative review process. The only abatement work identified at the mine site concerned the coal fines. The undisturbed diversion that eroded and ~~on~~ one segement had uncovered coal fines was repaired. No other work was performed on the channel.

As part of the administrative process the permittee had to submit a proposed erosion plan by 3/16/92. The plan was received on 3/16/92 by the Division and is currently under review.

Sediment Pond. Pond contained a small amount of runoff estimated at about 2'. Pond was stable and showed no recent evidence of discharge.

Subsidence. The subsidence cracks on the mesa were observed. When field work is performed on the silt fences, diversions as a response to the foregoing NOV's, the operator should repair or fill the subsidence cracks and sign the area as requested by Susan White.

Copy of report mailed to WSM/ Dwight Cassland; OSM/ Brent Smith; DOGM/ Joe Helfrich

Copy of report ~~given~~ filed to PFO

Inspector's signature Tom J. Malencik No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

3/30/92