0005

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Opt page

Partial:__ Complete: X__ Exploration:__
Inspection Date & Time: 10/5/93 10:00am - 4:45 pm
Date of Last Inspection: 9/30/93

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002
Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502
Type of Mining Activity: Underground X Surface__ Prep. Plant__ Other__
State Officials(s): Tom Munson
Company Official(s): Greg Poole
Federal Official(s): None
Weather Conditions: sunny
Existing Acreage: Permitted-480 Disturbed-30 Regraded-___ Seeded-30 Bonded-30
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: __Exploration/__Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	[ ]	[X]	[ ]
2. SIGNS AND MARKERS	[X]	[ ]	[X]	[ ]
3. TOPSOIL	[X]	[ ]	[X]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[X]	[ ]	[X]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	[ ]	[X]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[X]	[X]	[ ]	[ ]
d. WATER MONITORING	[X]	[ ]	[X]	[ ]
e. EFFLUENT LIMITATIONS	[X]	[X]	[ ]	[ ]
5. EXPLOSIVES	[X]	[X]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]	[X]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	[X]	[ ]	[ ]
8. NONCOAL WASTE	[X]	[X]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE ANXD RELATED ENVIRONMENTAL VALUES	[X]	[X]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[X]	[X]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[X]	[X]	[ ]	[ ]
12. BACKFILLING AND GRADING	[X]	[X]	[ ]	[ ]
13. REVEGETATION	[X]	[ ]	[X]	[ ]
14. SUBSIDENCE CONTROL	[X]	[X]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[X]	[X]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	[X]	[ ]	[ ]
b. DRAINAGE CONTROLS	[X]	[X]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[X]	[X]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	[X]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)_____(date)	[X]	[X]	[ ]	[ ]
20. AIR QUALITY PERMIT	[X]	[X]	[ ]	[ ]
21. BONDING & INSURANCE	[X]	[X]	[ ]	[ ]

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/002 DATE OF INSPECTION: 10/5/93

(Comments are Numbered to Correspond with Topics Listed Above)

1.) Permits - On September 30, 1993 the division received a plan from Western States Minerals regarding the J.B. King Reclamation and the abatement of NOV #91-32-6-1; #93-25-3-1; & #93-25-5-1. Field work and construction is to be completed within 45 days of approval of plans. These plans are being reviewed by the Division.

2.) Signs and Markers - The sign in place at J.B. King lists Western States Minerals as the permittee and the address as 4975 VanGordon St., Wheatridge, Colorado, 80033 and the telephone number as 303-425-7042. This address is considered the corporate address.

3.) Topsoil- N.O.V. 93-25-3-1 addresses the inadequacy of areas of the site which are failing in regards to erosional stability as this is directly related to the topsoil placed during reclamation.

4a.) Diversions - N.O.V. 91-32-6-1 was extended to September 30, 1993 on August 26, 1993. The Diversions were surveyed to determine the adequacy of design parameters for future reclamatiopn plans of the current channels.

4b.) Sediment ponds and impoundments- The sediment pond was dry at the time of inspection. The last pond inspection was submitted to the Division on 10/8/93 and indicated no problems. A certified annual report was received by the Division on January 11, 1993 based on an inspection carried out on December 24, 1992.

4d.) Water Monitoring- No water quality or quantity data has been submitted to the Division.
13. Revegetation - N.O.V. 93-25-5-1 was issued on 8/12/93 as failure to establish revegetation as specified in the approved permit (UMC 784.13 Reclamation Plan : General Requirements). The abatement date is November 12, 1993.

Copy of this Report:
Mailed to: Bernie Freeman (OSM), E. M. Gerick (WSMC)
Given to: Joe Helfrich (DOGM)

Inspector's Signature: Tom Munson #25 Date: 10/14/93